CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
East Quarter Corner of Section 27 Township 142 Range 27 5th P.M.	
STATE OF MINNESOTA, County of Cass	
At the corner location shown on the sketch:	
□ On found a	
☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)	
TX On 10/29/81 placed a cast iron monument at the lost position between the NE and SE corners of Sec. 27.	
SKETCH OF REFERENCE TIES	
<u> </u>	
4	
-N-	N 9 D du Oll Manda
	N & D in 8" Maple N 25 E 16.81'
	Scribed BT in lower blaze
Tonor braze	
N & D in 7" Ash N 75 W 21.56'	
N 75° W 21.56' Scribed BT in lower blaze  N & D in 8" Birch S 80° E 17.62'	
lower blaze N & D in 8" Birch	
,,	Scribed BT in
lower blaze	
( ∕ <b>3</b>	
N & D in 10" Birch	
SOUTH 16.33'	
Scribed BT in lower blaze	
BEARINGS ARE APPROXIMATE	
Statement of evidence relative to this corner location is on back of page. $260.598$	
I hereby certify that this document and the data	OFFICE OF THE COUNTY RECORDER
contained herein was prepared by me or under	County of Class
my direct supervision.	I hereby certify that this document was filed in
Lay H. Atevenon 12-2-81 SIGNATURE DATE	the Co. Recorders office at #10 A.M. on the 3 day of 2 A.D., 1981
Registration No. 12684	County Recorder Beulah Hendinhu
	By MS Deputy
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO. 260598

## Statement of Evidence:

- 1873 U.S. General Land Office survey set wood post for this corner and marked the following bearing trees: 4" Birch N 62° E 9 links and 5" Birch N 37 W 4 links.
- 1980 County Surveyor's Records in the Recorder's Office were checked and no resurvey information was found on this corner.
- 1980 U.S. Forest Service office in Cass Lake was contacted for information and no resurvey information was found on this corner.
- A traverse was run in cooperation with Bill Olson, USFS technician, between the SE and NE corners of Sec. 27. No evidence of this corner was found or of the two meander corners between this corner and the SE corner of Sec. 27. I therefor concluded that this corner was lost and reestablished it midway and on line between the SE and NE corners of Sec. 27.