CERTIFICATE OF LOCATION OF GOVERNMENT CORNER			
East Quarter Corner of Section 32 Township 140N, Range 30W, 5th P.M.			
STATE OF MINNESOTA, County of			
At the corner location shown on the sketch:			
On	found & <u>nothing</u>		
_		ed monument, removed monument (explain)	
⊠ On	n <u>09/03/82</u> placed a <u>Minnesota S</u> DATE monument.	tate Highway Department cast iron	
SKETCH OF REFERENCE TIES			
, .	SKETON OF K	The trace the same and the same	
4		Copper Nail & Disk	
- N-	Field Face tie to	In West side of 16" Norway	
	Old Scribed Bearing Tre	/¥ 50.18' N15°E	
	P. C.	1 / ★ 64.58' N43°E	
		Copper Nail & Disk In NW side of 10" White Pine	
		10" White Pine	
West 59.74' * 55.98' N80 E			
Copper Na	ail & Disk /	Copper Nail & Disk In North side of	
In South side of		7" Jack Pine	
	SECTION 32	SECTION 33	
		Was de	
Woods			
		1	
		All trees have double blazes. All bearings are magnetic.	
		555221.85 424 424,444	
Statement of evidence relative to this corner location is on back of page.			
3 de 1938			
I hereby ce	ertify that this document and the data	OFFICE OF THE COUNTY RECORDER	
contained herein was prepared by me or under		County of	
my direct supervision.		I hereby certify that this document was filed in	
James W. Nielsen 3/4/83 SIGNATURE DATE		the Co. Recorders office at Him A. M. on the	
SIGNATURE		4 day of <u>April</u> A.D., 19 8-3	
Registration No		County Recorder Cloudine Kaylan By M S ,Deputy	
⊠ Land Surveyor, □ Professional Engineer		By 1/2 ,Deputy	
Coun	ty Surveyor. County Engineer	DOCUMENT NO. 26 7938	

Statement of Evidence: East Quarter Corner of Section 32, Township 140 North, Range 30 West, 5th Principal Meridian.

The original Public Land Survey was run in 1865 and a wood post was set to mark the corner.

In 1907 Mr. John Curo, County Surveyor, called for a post at the corner.

In 1982 the Minnesota Department of Transportation found an old scribed bearing tree stump but did not find any corner evidence or any more records for this corner. A lost location fits the face blazes on the bearing tree and also fits the fence line going north. We set the corner at the lost location, midway and on line between the Northeast Corner of Section 32 and the Southeast Corner of Section 32.

For details and survey analysis contact the Minnesota Department of Transportation Surveys Office in Brainerd, Minnesota.