


Index No. L 25

CASS COUNTY LAND CORNER RECORD

T. 133 R. 30 M. 5TH Coordinates: X _____ Y _____
E 1/4 13 Corner common to sections 13 and 18-133-29



EXISTING SURVEYS

Original Government Survey

Year surveyed 1858
Original monument lost

Bearing Trees

Species	<u>PINE</u>	<u>PINE</u>
Diameter	<u>14"</u>	<u>15"</u>
Bearing	<u>S 8 1/2 W</u>	<u>S 37 E</u>
Distance	<u>182 LKS</u>	<u>313 LKS</u>

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

○ = Corner

Subsequent Corner Restoration

Year surveyed 1915 By John Curo
Location filed County Book 'B' P. 422-432
Monument SET HUB PROPORTIONALLY

Evidence of Subsequent Corner Restoration

Year of search 1998 By CCSO
Fd. in place 3/4" ODIP down 0.3' in
& Co RD. 36

Bearing Trees, Reference Objects

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Bearing Trees, Reference Objects

<u>P. Pole</u>	<u>P. Pole</u>	<u>W. Pine</u>
		<u>11"</u>
<u>119.90'</u>	<u>149.30'</u>	<u>95.25'</u>

L-25

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - Searcyville
Dean Anderson 1972

Jul 2001 J. Hansen # 14712
Cert. of sur. shows mon found

- corner 11/4/02 GPS CCSO
PK on E Co. Rd. # 36

Remuneration certificate prepared _____
Filed at _____

By _____
Date _____