


Index No. A 9

CASS COUNTY LAND CORNER RECORD

T. 139 R. 28 M. 5TH Coordinates: X _____ Y _____
NE 5 Corner common to sections 4, 5 AND 32, 33-140-28



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing Trees			
	TAM.	TAM.	TAM.	TAM.
Diameter	10"	7"	8"	11"
Bearing	N54 1/4 E	N8 1/2 W	S 33 E	S 34 W
Distance	65 LKS	76 LKS	57 LKS	55 LKS

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed 1919 By BEN CLARK
Location filed COUNTY BOOK 7 P. 328
Monument END IRON POST (W. EDGE OF A LITTLE BROOK)
1922 COUNTY RESURVEY "E-9" BEN CLARK

Evidence of Subsequent Corner Restoration

Year of search 1980 By CO. HWY. DEPT.
END 2" CAPPED I.P. (CO. RP# 47)
1942, JOHN CURR, BOOK D P. 325 END I.M.
1939 - CCC - Washburn Lake - BK# 12 P. 37
start west from corner.
1941 - CCC - BK# 15 P. 37. Start North from I.P.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance

A-9

Subsequent Corner Restoration

Year surveyed 1938 By CCC
Location filed Washburn Lake - BK # 13 P. 8
Monument at 5341' from east - End I.P. 3' North

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - WABEDD SPRINGS
JOHN M. GREENE 1927
1998 - Landecker & Assoc. - Survey info
indicates 2" capped IP in place.
2000 - CCSD - Fnd. inpl. 2" capped I.P.
E CREEK is 1/2 E due North of CORNER.
REF. TIES:
15" Dead Cedar S 70° W 135.88'
11" Tamarack (TAG) S 57° W 191.83'
12" Tamarack S 31° W 178.96'
* dist. to dbl. hd. nail

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____