


T. 143 R. 25 M. 574 Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

E 14 13 Corner common to sections 13



EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1867  
 Original monument Post

**Bearing Trees**

Species	<u>TAM.</u>	<u>TAM.</u>	_____	_____
Diameter	<u>9"</u>	<u>6"</u>	_____	_____
Bearing	<u>N45W</u>	<u>S10W</u>	_____	_____
Distance	<u>26 LKS</u>	<u>32 LKS</u>	_____	_____

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration**

Year of search 1914 10-14 By Terry Freeman  
 Found 1" iron pipe w/alum. cap up 16" left as found  
316-95 Cert Filed by Terry Freeman, RLS 21367  
Doc # 365396

**Bearing Trees, Reference Objects**

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

**Bearing Trees, Reference Objects**

<u>Ash</u>	<u>Burr Oak</u>	<u>Burr Oak</u>
<u>11"</u>	<u>16"</u>	<u>19"</u>
<u>N3E</u>	<u>S86W</u>	<u>S20W</u>
<u>14.44</u>	<u>12.11</u>	<u>7.64</u>

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument Jan 2005 T Freeman #21367  
Cert. of Survey shows monument found

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_