

Form 874-0—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

B-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57N R. 26W 4th Mer.
N 1/16 Corner common to Sections

4, and 5

Corner consists of a 3/4" Iron Pipe (~~rod~~) in place

State condition Good

Dimensions above ground 3/4 X 3 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? Set by F.S.

Edw. Peterson

(Signature)

July 30, 1937

(Date)

Jr. Asst. to Tech.

(Title)

B-9

Corner is on top of high hill which slopes off steeply to the west.

Corner again.

Give any further facts which will aid in finding this

chains distant.


0.23

From which this Corner bears S58°30' E

side of Truck Trail 570

tree 14 inches diameter, on the North

Metal Location Poster is on a ~~North~~ Pine



(Make sketch of topography near Corner)

T 57N R 26W 4th Mer.

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

B-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 57N R. 26W 4th Mer.

N 1/16

Corner common to Sections

4

and 5

Corner consists of a 3" Iron Pipe (~~rod~~) in place

State condition Good

Dimensions above ground 2 X 3 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner no?

If not, why? Set by F.S.

L. W. Peterson
(Signature)

July 30, 1937
(Date)

Jr. Asst. to Tech.
(Title)

B-9

Corner is on top a high hill which slopes off steeply to the west.

Corner again.

Give any further facts which will aid in finding this

chains distant.

0.25

from which this Corner bears S58°30' E

side of Truck Trail 570

tree 14 inches diameter, on the

Metal Location Poster is on a ~~North~~ pine

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)