

U. S. Department of Agriculture
FOREST SERVICE

L 9

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 25 S. 5 Mer.

1/2 Corner common to Sections
16, and 17

Corner consists of a Iron Pipe ~~mark~~ in place
State condition Good

Dimensions above ground 12" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

B	L	A	N	K
N	W	S		

B	L	A	N	K
NW	SW	SE	NE	

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species No. B.T.'s. _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No.

If not, why? County Corner (probable)

Raymond T. DeFaut

Raymond T. DeFaut

(Signature)

Jr. Civil Engineer

(Title)

1-23-40

(Date)

UNITED STATES DEPARTMENT OF THE INTERIOR

Corner Corner

Corner again

Give any further facts which will aid in finding this


by post chains distant

from which this Corner bears

side of post

and 6" inches diameter, on the Corner

Metal Location Poster is on a Fence Post



(Make sketch of topography near Corner)

Mer. L-9

5

25

R.

T. 141

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

L-9

CHIPPEWA NATIONAL FOREST


CORNERS OF THE PUBLIC SURVEY

T. 141 R. 25 Mer.

1 Corner common to Sections
16, and 17

Corner consists of a Iron Pipe in place
State condition Good

Dimensions above ground 12" inches
Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species No. B. T. 's.

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No.

If not, why? County Center (probable)

Raymond T. DeFaut
Raymond T. DeFaut

(Signature)
Jr. Civil Engineer

1-23-40

(Date)

CORNERS OF THE PUBLIC SURVEY

Corner again

(Give any further facts which will aid in finding this


corner distant

from which this corner bears

side of

inches diameter, on the corner

Metal Location Poster is on a



(Make sketch of topography near corner)