

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

P-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 27 5th Mer.

Quarter Corner common to Sections

23, and 24

Corner consists of a Iron pipe (not) in place

State condition With brass cap

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Sec.
23

Sec.
24

--

--

BT

BT

--

--

Species Cedar Cedar

Diameter 5" 4"

Bearing N60W N81E

Distance 11 .33

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Walter Haberle

(Signature)

Leader

(Title)

11/27/39

(Date)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on the berrings trees



(Make sketch of topography near Corner)

T. 147 R. 27 5th Mer.

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

821

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 137 R. 27 5th Mer.
Quarter Corner common to Sections

23, and 24

Corner consists of a iron pipe (not) in place

State condition With brass cap

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

323	324		
Bt	BT		

Species Cedar Cedar

Diameter 5" 4"

Bearing N60W N21E

Distance 11 .33

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Walter Haberle

(Signature)

Leader

(Title)

11/27/39

(Date)

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears


side of

tree inches diameter, on the

trees

Metal Location Poster is on a

The bearing



(Make sketch of topography near Corner)

T. 147 R. 27 5th Mer.

U. S. Department of Agriculture

FOREST SERVICE

P-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 27 5th Mer. Quarter Corner common to Sections

23, and 24

Corner consists of a Iron pipe (not) in place State condition With brass cap

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

Diagram showing cardinal positions N, W, S, E with corresponding boxes.

N W S E

Diagram showing diagonal positions NW, SW, SE, NE with corresponding boxes.

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Table for sketching markings of Bearing Trees (S23, S24, BT) with empty boxes for bearings and distances.

Species cedar cedar Diameter 5" 4" Bearing N60W N21E Distance .11 .33

Do you believe this to be a genuine Land Office Corner? Yes If not, why?

Walter Haberle

(Signature)

Leader

(Title)

11/27/39 (Date)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a the bearing trees



(Make sketch of topography near Corner)

T. 147 R. 27 5th Mer.