

Corner again.

Give any further facts which will aid in finding this

39, chain/distant

from which this Corner bears


SE NW

side of

tree 9 inches diameter, on the

Metal Location Poster is on a

30



(Make sketch of topography near Corner)

V-5  
Mer.

522

R. 31

T. 147

U. S. Department of Agriculture  
FOREST SERVICE

V-5  
V-5

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 31 5<sup>th</sup> Mer.

Section Corner common to Sections  
29, 30, 31, and 32

Corner consists of a 4 L O (not) in place  
State condition Good

Dimensions above ground 2 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T 147
R-31
S 30

T 147
R-31
S-32

--

--

BT
----

BT
----

--

--

Species Birch Birch \_\_\_\_\_

Diameter 9" 6" \_\_\_\_\_

Bearing N49W S16E \_\_\_\_\_

Distance 39ch 58ch \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

C. C. Case  
(Signature)

12/5/35  
(Date)

(Title)

V-5