

Ben Meadows Co.
101520

LIETZ
LEVEL BOOK
No. 815135

#119

T141N R26W

Sec. Cor. $\frac{3}{10} \frac{2}{11}$

ORIG.

Set wood Post $\frac{1}{2}$ point at old post

Spruce 7 N27W 16 lks = 10.6'

Ed. stp. $\frac{1}{3}$ by no scribe visible at brg. $\frac{1}{2}$ dist.

Spruce 8 N35E 13 lks. = 8.6'

No evidence in winter

Spruce 10 S60E 28 lks = 18.5'

No evidence in winter

Spruce 8 S34W 24 lks = 15.8'

New fallen tree w/scar stp rotted at brg. $\frac{1}{2}$ dist. ^{S47°W 153'} w/ old FSLP

Set 2" Dia. x 5' long steel pipe w/brass cap

Tam. 7" N35°E 26.9' T141NR26WSZBT

Tam. 8" S49°E 24.7' S11BT

Tam. 7" S66°W 53.2' S10BT

Tam. 9" N10°W 20.9' S3BT

Set 8' steel sign post due north 3.1'

FS sign S4-4 4-1-75

Curtis R. Hansen
Jack O. Brandy

fd. 1 1/2" OD IRON PIPE marking corner

No info as to who set iron pipe

Ed. FSLP on down B. Spruce All rusted

Iron found at corner was on top of wood post

DN COR. CARD CK
2-20-85

TISON R26W

1/4 Corner Bet. 9-16

ORIG.

Wood post 4" x 4" x 48" with scribe 1/4 S
of NW 22.3'

To perpetuate this corner I set 5' x 2" dia.
steel pipe with brass cap

B. Spruce 7" S10°W 83.4' mkd 1/4 S16 BT

Ash 6" S21E 29.5' mkd 1/4 S16 BT

B. Spruce 9" N82°E 93.0' mkd 1/4 S9 BT

Steel sign Post 8' 54-2-54-4 North 3.0'

Steel sign Post 8' 54-2 East 3.4'

4-4-75

Jack D. Brandy
William B. Wells

A-4-75

T150N R26W

1/4 Bet. Sec. 16-17

ORIG.

fd. orig. tree for Cor. post

also orig. Cedar BT NW

Field Book

To perpetuate this corner I set 2" Dia.
x 5' long steel pipe with brass cap

Cedar 10" N52E 39.3' mkd. 1/4 S16 BT

Cedar 10" S67°E 19.0' mkd. 1/4 S16 BT

Cedar 10" S50 W 48.1' mkd. 1/4 S17 BT

Steel sign post due east 3.2' w/54-4

4-4-75

Clinton R. Kramer

Jack O. Handy

Arthur B. Wells

4-4-75

570' East of 16' Balsam with FSLP on East
side of Co. Rd.

T149 N R27W

Co. Remonumentation

By K.K. Russell Co. Surveyor 1922

E'116 Bet. Sec.'s. 17 & 20

Set iron post

found 1"00 iron in place 6" above ground

4-7-75 *Control R. K. Russell*

Witnessed by

J. Pine 10" ^{Mag.} N72W 25.3' ^{True} N65W 25.3'

Now well rotted J. Pine stp. at ^{Mag.} ^{True} brg ^{Mag.} dist.

J. Pine 14" N88°E 29.2' S87°E 29.2'

Now J. Pine stp. with scribe BT visible

To perpetuate this corner I set 2" Dia. x 5' long
steel pipe with brass cap.

T149 N R27W
E'116 S17
S20
1975

B. Spruce 10 S81 W 61.9' E'116 S20 BT

Aspen 8 S46 E 28.3' E'116 S20 BT

B. Spruce 7 N65 W 66.0' E'116 S17 BT

B. Spruce 10 N20 W 79.7' E'116 S17 BT

Set 8' steel sign post due East 2.7 w/54-2

Set 8' steel sign post due South 3.5 w/54-2:544

4-10-75
JG CK

Put FSLP on 6" Balsam S21°E 4.0'
fd. FSLP on 12" Aspen 102' south of corner
on south side of old R.R. Grade near

woods trail - old blazes from Aspen to corner

Copied into field Book

T149 N R27W

Sec. Cor. 16-17-20-21

Co. iron pipe ^{1/2} Gait Birch SE.

Spruce 7 ³⁴ S28W 32.9

Balsam 8 ³² S38E 13.5

Spruce 8 ⁶⁹ N75W 5.2

Balsam 10 ²² N16E 30.9

Tapered square corner 1 set 2" dia. X 5' long
with brass cap

BT'S.

T149 N R27W

17 | 16
20 | 21
1975

Chained East along blue line 1260'

Chained S2°E To end of fence line running N-S
wye in fence SE-SE no iron found - dist. 1336'S

Put ESK Pon 5' Balsam ^{Approx.} corner is N 30°E - 50'

J.G.-CK

49-75

T149N R27W

Center 1/4 Sec. 20

Co. iron pipe fd 1" OD IRON IN PLACE

Spruce 6" S13W 28.9'

Now rotted stp at Brg.

Spruce 6" S25E 21.2'

Now 7' stub cut off with scribe marks visible
at mag. Brg. 1/2 dist.

Set steel pipe 2" Dia. x 5' long with brass cap

T149N R27W
C/A S20

1975

B. Spruce 6 S63°E 8.2' mkd C/A S20 BT

B. Spruce 7 S12°E 28.2' C/A S20 BT

B. Spruce 7 S47°W 38.5' C/A S20 BT

B. Spruce 8 N62W 9.0' C/A S20 BT

8' steel post due south 3.1 5A-2

8' steel post due North 4.8 5A-2 1/2 5A-4

4-10-75

Copied into field Book

T147N R31W

C/4 SEC. 22

8-22-78

2" IRON PIPE Fd. 18" W/ FLANGES

BRASS CAP AND 14" PIPE GONE

Fd. W. OAK 17" N86W - 43.6' SCRIBE OVERGROUND

ASPEN FALLS AT EAST EDGE OF RD.

SET 5 1/2 X 5 1/2 X 24 CONCRETE CYLINDER

RESET GLO IRON MKO T147NR31W

AT NORTH EDGE

C/4 S22
1978

WITNESSED BY

RLS NO 12261

W. OAK 17 N86W 43.6' RESCRIBED BT

W. OAK 11 S74E 42.31 MKO C/4 S22 BT

N. PINE 19 N9E 127.30 MKO C/4 S22 BT

4X4X8 SET DUE EAST 21.51

OPEN LINE BRS. EAST FROM COR.

COPIED IN FIELD BOOK

8-31-78 CAK

END OF
BOOK 119