CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
Northeast Corner of Section 17 , Township 133N , Range 20w , 5th P.M.	
STATE OF MINNESOTA, County of Grow Willing CASS	
At the corner location shown on the sketch:	
On 6/23/77 found a _axle shaft in poured concrete	
* Township blade striking monument causing road hazard- unable to lower  □ left monument as found, □ lowered monument, □ removed monument (explain) *	
C) On 6/23/77 placed a 1-1/2" Capped iron pipe down 6".	
SECTION 8 SKETCH OF REFERENCE TIES SECTION 9	
1	1
Copper nail and disk in	Copper nail and disk in 20" Jack Pine up 0.3' on
6" Jack Pine up 0.5' on north side.	northwest side
38.23'	
	*/
1 +	
Copper nail and disk in	
6" Norway Pine up 0.4' on northwest side	T.H. 210 84.08.  Copper nail and disk in
Power Pole up 0.2' on East side.	
THE STATE OF THE S	
JUN - 9 2006 U	
17/33/29	
SECTION 17 CASS COUNTY SURVEYOR SECTION 16	
Statement of evidence relative to this corner location is on back of page.	
I hereby certify that this document and the data OFFICE OF THE COUNTY RECORDER	
contained herein was prepared by me or under	County of
my direct supervision.	I hereby certify that this document was filed in the Co. Recorders office atM. on the
alphonse P. Welle 6/29/77 SIGNATURE DATE	day of A.D., 19
Registration No	County Recorder,Deputy
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO,Deputy