CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
Northeast Corner of Section 26 ,Township 138N , Range 30W , 5th P.M.	
STATE OF MINNESOTA, County of <u>Cass</u>	
At the corner location shown on the sketch:	
On 06/01/78 found a 2½" capped iron pipe.	
🖾 left monument as found, 🗆 lowered monument, 🗅 removed monument (explain)	
Onplaced a	
SKETCH OF REFERENCE TIES	
SECTION 23	SECTION 24
*	
-N- CULTIVATED	CULTIVATED
Copper nail & disk	Spike in Corner Fence
In Corner Fence Post, Up 1.5' on NE side.	Post up 1.5 feet on Southeast side.
44.77	S8.56'
	F/
TOWNSHIP	ROAD
TOWNSHIP	ROAD
TOWNSHIP	(*67.37'
TOWNSHIP	* (**67.37' \$44.66' Copper nail & disk in 14"
TOWNSHIP	* (*67.37' 44.66' Copper nail & disk in 14" Nail and Norway Pine on SW side Washer face Up 2.0 feet
CULTIVATED	**67.37' 44.66* Copper nail & disk in 14" Nail and Norway Pine on SW side Washer face Up 2.0 feet of 10" Norway Pine.
	* (*67.37' 44.66' Copper nail & disk in 14" Nail and Norway Pine on SW side Washer face Up 2.0 feet Of 10" Norway
	**67.37' 44.66' Copper nail & disk in 14" Nail and Norway Pine on SW side Washer face Up 2.0 feet of 10" Norway Pine.
CULTIVATED	* (**67.37' 44.66' Copper nail & disk in 14" Nail and Norway Pine on SW side Washer face Up 2.0 feet of 10" Norway Pine. NORWAY PINE TIMBER
	**67.37' 44.66' Copper nail & disk in 14" Nail and Norway Pine on SW side Washer face Up 2.0 feet of 10" Norway Pine.
CULTIVATED	* (*67.37' 44.66' Copper nail & disk in 14" Nail and Norway Pine on SW side Washer face Up 2.0 feet of 10" Norway Pine. NORWAY PINE TIMBER SECTION 25
CULTIVATED SECTION 26 Statement of evidence relative to this corner local lateral control of the data.	** 44.66* Copper nail & disk in 14" Nail and Norway Pine on SW side Washer face Up 2.0 feet of 10" Norway Pine. NORWAY PINE TIMBER SECTION 25 cation is on back of page. OFFICE OF THE COUNTY RECORDER
CULTIVATED SECTION 26 Statement of evidence relative to this corner local land the data contained herein was prepared by me or under	* (*67.37' 44.66' Copper nail & disk in 14" Nail and Norway Pine on SW side Washer face Up 2.0 feet (of 10" Norway Pine. NORWAY PINE TIMBER SECTION 25 Cation is on back of page. OFFICE OF THE COUNTY RECORDER County of (455)
CULTIVATED SECTION 26 Statement of evidence relative to this corner local land the data	** 44.66* Copper nail & disk in 14" Nail and Norway Pine on SW side Washer face Up 2.0 feet of 10" Norway Pine. NORWAY PINE TIMBER SECTION 25 cation is on back of page. OFFICE OF THE COUNTY RECORDER
CULTIVATED SECTION 26 Statement of evidence relative to this corner local land the data contained herein was prepared by me or under	A44.66' Copper nail & disk in 14" Nail and Norway Pine on SW side Washer face Up 2.0 feet of 10" Norway Pine. NORWAY PINE TIMBER SECTION 25 Cation is on back of page. OFFICE OF THE COUNTY RECORDER County of Cass I hereby certify that this document was filed in the Co. Recorders office at 11.60 A.M. on the 14 day of Caunty Recorder County Recorder Seulal Henchicles
CULTIVATED SECTION 26 Statement of evidence relative to this corner local land the data contained herein was prepared by me or under my direct supervision. Johnson P. Welle 7/31/78 SIGNATURE DATE	A44.66' Copper nail & disk in 14" Nail and Norway Pine on SW side Washer face Up 2.0 feet (of 10" Norway Pine. NORWAY PINE TIMBER SECTION 25 Cation is on back of page. OFFICE OF THE COUNTY RECORDER County of Cass I hereby certify that this document was filed in the Co. Recorders office at Line A.M. on the Lyday of Cause A.D., 19 78

Statement of Evidence: Northeast Corner Section 26, Township 138 North, Range 30 West, 5th Principal Meridian.

The Original Public Land Survey was run in 1865 by Mr. George B. Wright and a wood post was set to mark the corner.

In 1907 Mr. John Curo set a $2\frac{1}{2}$ capped pipe at the original location from the original bearing trees.

In 1978 the Minnesota Department of Transportation recovered Mr. Curo's pipe.

For details and survey analysis contact the Minnesota Department of Transportation District Surveys Office in Brainerd.