| | OF GOVERNMENT CORNER 2,Township 135N,Range 31W,5thP.M. |
|---|--|
| STATE OF MINNESOTA, County of Cass | , TOWNSHIP, Trange,, Trange |
| At the corner location shown on the sketch: | |
| | |
| DATE | |
| • | red monument, 🗆 removed monument (explain) |
| On 12/27/78 placed a 2" square s | teel post with Mn/DOT cap. |
| SKETCH OF REFERENCE TIES | |
| SECTION 29 | SECTION 28 |
| | N42°E |
| N40°W | Copper nail & disc in 10" Double blazed white oak up |
| Copper nail & Disc in 8" Double Blazed Twin Maple | 96.85'\ 997.85' 1.0' SE side |
| 1.0' up west side. | Copper nail & Disc in 6" Double Blazed Twin Elm 1.0' N230E |
| | |
| | Co. Rd. 35 |
| · · · · · · · · · · · · · · · · · · · | |
| NOTE: All distances are slope chained | 50.14' Copper nail & disc in 12" Double blazed basswood Up 1.0' N.E. side. S50°E |
| SECTION 32 | Uncorrected Magnetic Bearings SECTION 33 |
| Statement of evidence relative to this corner location is on back of page. | |
| I hereby certify that this document and the data contained herein was prepared by me or under | OFFICE OF THE COUNTY RECORDER County of |
| my direct supervision. alphonse R. Delle 2/15/79 SIGNATURE DATE | I hereby certify that this document was filed in the Co. Recorders office at 11:55 A. M. on the 24 day of Ap. 1979 |
| Registration No. 11873 | County Recorder Benlah Hendrichs By, Deputy |
| ☑ Land Surveyor, ☐ Professional Engineer | By,Deputy |
| ☐ County Surveyor. ☐ County Engineer | DOCUMENT NO. 247568 MIKUTILIN |

Statement of Evidence: Northeast Corner Section 32, Township 135 North, Range 31 West, 5th Principal Meridian

The original public land survey was run in 1870 and a wood post was set to mark the corner.

The township records indicate that the area roads were inplace in 1898.

No other records could be found and longtime area residents knew of no corners inplace.

In 1979 the Minnesota Department of Transportation set this corner at the occupation fences north-south and the road east-west. This location agrees with a proportionate distance to the occupation quarter and section corners for $2\frac{1}{2}$ miles west and one mile east. This indicates that the fence locations are a direct result of previous survey work.

For details and survey analysis contact the Minnesota Department of Transportation Surveys Office in Brainerd.