CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
Northeast Corner of Section 27 , Township 142 , Range 27 , 5th P.M.	
STATE OF MINNESOTA, County ofCass	
At the corner location shown on the sketch:	
On 1/21/81 found a 2" iron pipe set by R.F. Schneider in 1971.      DATE	
☐ left monument as found, ☐ lowered monument, ☒ removed monument (explain)	
On 10/29/81 placed a 2" x 60" iron pipe with marked 3" brass cap in place of the found pipe.	
SKETCH OF REFERENCE TIES	
4	
X X	N & D in 10" Balsam North 8.04'
N & D in 12" Balsam; West 9.83'	
· *	米 N & D in 5" Balsam S 65° E 18.65' Scribed BT in lower blaze
N & D in 10" Balsam	
S 3 <sup>0</sup> W 9.85' Scribed BT in lower blaze	· ·
TOWER STUDE	,
BEARINGS ARE APPROXIMATE	
Statement of evidence relative to this corner location is on back of page.	
260593	
I hereby certify that this document and the data contained herein was prepared by me or under	OFFICE OF THE COUNTY RECORDER  County of
my direct supervision.	I hereby certify that this document was filed in
Day H. Stevenson 12-2-81 SIGNATURE DATE	the Co. Recorders office at 10:45 A.M. on the  3 day of Dec. A.D., 1981
Registration No. 12684	County Recorder Beneficher
🕱 Land Surveyor, 🗆 Professional Engineer	By M S Deputy
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO. 260593

## Statement of Evidence:

- U.S. General Land Office survey set wood post for this corner and marked the following bearing trees: 6" Fir N 70° E 6 links, 7". Fir S 58° W 18 links, 8" Poplar N 25 W 8 links, and 5" Poplar S 10° E 21 links.
- 1980 U.S. Forest Service office in Cass Lake was contacted for information and and no resurvey information was found on this corner.
- 1980 County Surveyor's Records in the Recorder's Office were checked and no resurvey information was found on this corner.
- R.F. Schneider, RLS, found a rotted wood post at the approximate corner. An 8" Balsam with a USFS yellow tag was found 10' to the west. After traversing the north line of Section 27, the wood post was accepted as the corner. A 2" iron pipe was set in the remains of the post and ties taken: 8" Balsam North 7.62', 8" Balsam West 9.40', and 8" Balsam South 9.60'. Evidence of an old blaze-line was found running west to the lake and evidence of previous surveys was found to the north along Swift Lake. However, no record or information as to who did it was found.
- I searched the corner area and found no other evidence of the corner. Traverses were run to known corners north, south, east, and west. Analysis of this information gave no further information. The approximate double proportion position falls 23 feet east and 28 feet south of the pipe. I accepted the pipe set by R.F. Schneider at the location of the found wood post as the perpetuated position of this corner. I replaced the pipe with a USFS monument.