CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
East Quarter Corner of Section 28, Township 142, Ronge 27, 5th P.M.	
STATE OF MINNESOTA, County of	
At the corner location shown on the sketch:	
On 1/12/81 found a USGLO Brass capped iron pipe in good condition. DATE If left monument as found, D lowered monument, D removed monument (explain)	
SKETCH OF REFERENCE TIES	
4	
_ NI	·
Center of 14" R. Oak 1919 GLO BT	N & D in 6".R. Oak N 5° E 24.10' Scribed BT in lower blaze
1919 GLO BT N 72° W 64.0'	
Q-1	,
0. 3	
	N & D in 8" R. Oak East 23.15'
N & D in 6" R. Oak S 56 W 3.41' Scribed BT in lower blaze	Scribed BT in lower blaze
BEARINGS ARE APPROXIMATE	
Statement of evidence relative to this corner location is on back of page. よんの 59 に	
I hereby certify that this document and the data contained herein was prepared by me or under	OFFICE OF THE COUNTY RECORDER County of
my direct supervision.	I hereby certify that this document was filed in
Day H. Stevenon 12-2-81	the Co. Recorders office at 11:00 A.M. on the 3 day of Dec. A.D., 198/
Registration No. 12684	County Recorder Beneal Herdinal
☑ Land Surveyor, □ Professional Engineer	By M S ,Deputy
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO. 260596

Statement of Evidence:

- U.S. General Land Office survey set wood post for this corner and marked the following bearing trees: 6" Poplar S 48° E 15 links and 8" Blk. Oak N 80 W 33 links.
- U.S. General Land Office resurvey could find no evidence of this corner. The corner was reestablished by lost methods midway and on line between the SE and NE corners of Sec. 28. Two bearing trees were marked: 10" Poplar S 3° E 191 links and 6" R. Oak N 72½° W 97 links. An iron pipe with a marked brass cap was set for the corner.
- The brass cap monument was found in good condition. The 1919 GLO R. Oak bearing was found at the record bearing and distance. Center of the tree was rotten and no scribe marks were found. Healed over blaze scar was evident.