CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
C - E - SE 1/64 Corner of Section 8 ,Township 141 ,Range 29 , 5th P.M.	
STATE OF MINNESOTA, County of CASS	
At the corner location shown on the sketch:	
☑ On6/17/81found oGLO brass cap monument in place as set in 1918.	
☑ left monument as found, ☐ lowered monument, ☐ removed monument (explain)	
□ Onplaced a	
UATE	
SKETCH OF REFERENCE TIES	
Monument Marked:	
S8 . TR 1570	
AP1 AP2	\ .
TR TR.	`,
1601 1603	<u>~</u>
Nail in # # G	
N:36 W 17.45' Nail in Scribed 9" W. Oak	
Scribed	9" W. Oak N 76. E 69.20'
	⊈ Scribed
	<u>,</u>
MARSH	<i>/</i> ·
Statement of evidence relative to this corner los	BEARINGS ARE APPROXIMATE
260984	
I hereby certify that this document and the data	OFFICE OF THE COUNTY RECORDER
contained herein was prepared by me or under my direct supervision.	County of
1 1 14	I hereby certify that this document was filed in the Co. Recorders, office at 9:18 A.M. on the
SIGNATURE 12-23-81	31 day of Dec. A.D., 1981
Registration No. 17684	County Recorder Beneal Herdrich
🕱 Land Surveyor, 🗆 Professional Engineer	By M S ,Deputy
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO. 26 0 984

Statement of Evidence:

- 1918 U.S. General Land Office dependent resurvey established this corner and an iron pipe with a marked brass cap was set to mark the corner.
- USFS technician Gary Brama found the GLO brass cap monument in place flush with the water surface in boggy marsh. Chained measurements were made east and west to 1/16th corners. The distances agreed well with the GLO distances. Two bearing trees were marked and are shown on this certificate. A steel sign post was set on the north side of the corner.
- On Dec. 8, I visited the corner and found items as per 1980 USFS report. The monument is in good shape and has not been disturbed. Since the distances check good east and west, accept the corner as being in the same location as set in 1918.
- County Surveyor's Records in the Recorder's Office were checked and no resurvey information was found on this corner.