CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
NORTH QUARTER Corner of Section 17, Township 141, Range 29, 5th P.M.	
STATE OF MINNESOTA, County of	
At the corner location shown on the sketch:	
On 7/2/80 found o GLO brass cap monument as set in 1918. On 7/2/80 found o GLO brass cap monument as set in 19	
☑ left monument as found, ☐ lowered monument, ☐ removed monument (explain)	
Onplaced a	
SKETCH OF REFERENCE TIES	
1	
4	
	(1918-GLO-BT)
12" W. Oak N 45 E 23.76'	
Scribed Scribed	
Nail in	
8" Elm	
S:54 W 12.39'	
	1
3	
(1918-GLO-BT)	
d'	18".R. Oak. S 10° W 61.38'
	Scribed
Statement of evidence relative to this corner location is on back of page.	
260986	
I hereby certify that this document and the data contained herein was prepared by me or under	OFFICE OF THE COUNTY RECORDER County of
my direct supervision.	I hereby certify that this document was filed in
Mary H. Stevenson 12-15-81 SIGNATURE DATE	the Co. Recorders office at 2:20 A. M. on the
SIGNATURE DATE	County Recorder Bulch Hendrich
Registration No. <u>17684</u> Market Land Surveyor, Professional Engineer	By M S ,Deputy
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO. 260 986
in County Surveyor, in County Linguiser	

Statement of Evidence:

- 1873 U.S. General Land Office survey set wood post for this corner and marked the following bearing trees: 5" Birch N 72 E 17 links and 3" Poplar S 31 E 14 links.
- 1918 U.S. General Land Office dependent resurvey found the corner marked by a decayed wooden stake, marks obliterated. An iron pipe with a marked brass cap was set to mark the corner. The following bearing trees were marked: 8" W. Oak N 44-30 E 36 links and 10" R. Oak S 10-15 W 93 links. No trace of the original bearing trees was found.
- USFS technician Gary Brama found the GLO brass cap monument in place up 8". Both bearing trees were found standing and rescribed "BT". Also, one new bearing tree was marked and is shown on this certificate: Steel sign post were set north and east of the corner.
- 1981 On Dec. 8, I visited corner area and found items as per 1980 USFS report. Healed over scars were evident on the GLO bearing trees.
- 1981 County Surveyor's Records in the Recorder's Office were checked and no resurvey information was found on this corner.