P	
CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
WEST 1/16th Corner of Section 9 & 16, Township 141, Range 29, 5th P.M. STATE OF MINNESOTA, County of CASS	
At the corner location shown on the sketch:	
On 7/8/80 found o GLO brass cap monument as set in 1918.	
☑ left monument as found, □ lowered monument, □ removed monument (explain)	
□ Onplaced a	
SKETCH OF REFERENCE TIES	
6" N	ail in 'W. Oak 39 E 33.48' cribed
¥ \ MARSH \	Nail in 4" W. Oak N 65 E 9.16' Scribed
<u>*</u>	
	Nail.in 9" R. Oak. S 72 E 41.94' Scribed
	BEARINGS ARE APPROXIMATE
Statement of evidence relative to this corner location is on back of page. 260989	
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.	OFFICE OF THE COUNTY RECORDER County of
Registration No. 12-684	the Co. Recorders office at 9.23 A. M. on the 31 day of A.D., 19 81 County Recorder Beach Handrich
✓ Land Surveyor, □ Professional Engineer	By M. S,Deputy
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO. 26 0 989

Statement of Evidence:

- U.S. General Land Office dependent resurvey established this corner and an iron pipe with a marked brass cap was set to mark the corner. The following bearing trees were marked: 14" R. Oak N 3-45 E 161 links and 10" Maple S 89-30 E 199 links.
- 1970 USFS technician L. Witthoeft found bent GLO brass cap monument.
- 1980 USFS technician Jim Schoonover found bent GLO brass cap monument leaning south-southeast. No evidence was found of the GLO bearing trees. Three new bearing trees were marked and are shown on this certificate.
- In May USFS crew ran traverse from the N 1 corner of Sec. 16 west to this corner. They measured 970.05' to the straight part of the base. This compared well with the GLO distance of 14.70 chains (970.2').
- 1981 On Dec. 8, I visited corner and found items as per 1980 USFS report.
- 1981 County Surveyor's Records in the Recorder's Office were checked and no resurvey information was found on this corner.