

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


SOUTH SIXTEENTH Corner of Section 22&23, Township 141, Range 29, 5th P.M.

STATE OF MINNESOTA, County of CASS

At the corner location shown on the sketch:

- On 7/17/80 found a marked GLO brass cap monument in good condition.
DATE
- left monument as found, lowered monument, removed monument (explain)
- On _____ placed a _____
DATE

SKETCH OF REFERENCE TIES



BEARINGS ARE APPROXIMATE

Statement of evidence relative to this corner location is on back of page. 261359

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Ray H. Stevenson 2-1-82
SIGNATURE DATE

Registration No. 12684

- Land Surveyor, Professional Engineer
 County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER

County of Cass

I hereby certify that this document was filed in the Co. Recorders office at 9:40 A.M. on the 2 day of Feb A.D., 1982

County Recorder Beneah Herdiche

By MS, Deputy

DOCUMENT NO. 261359

Statement of Evidence:

- 1918 U.S. General Land Office dependent resurvey established this corner and an iron pipe with a marked brass cap was set to mark the corner. The following bearing trees were marked: 5" J. Pine N 50-30 E 47 links and 10" N. Pine S 46-15 W 240 links.
- 1980 USFS technician W. Olson found the marked GLO brass cap monument in place in good condition up 6". Both 1918 GLO bearing trees were found alive at record bearing and distance. Two new bearing trees were marked and are shown on this certificate. A steel sign post was set 4' south of the corner.
- 1981 County Surveyor's Records in the Recorder's Office were checked and no resurvey information was found on this corner.
- 1982 Visited corner on Jan. 29 and found items as per 1980 USFS report. Accepted found monument as marking the same position as when set in 1918. The two 1918 bearing trees both had visible scribing. (W. Olson's report had the distances to the 1918 bearing trees reversed).