CERTIFICATE OF LOCATION OF GOVERNMENT CORNER
CW $1/16$ Corner of Section 1 , Township 141 , Range 30 , 5 P.M.
STATE OF MINNESOTA, County ofCASS
At the corner location shown on the sketch:
On 10-7-81 found a 1"x36" iron pipe with brass cap standing in good condition.
≥ left monument as found, □ lowered monument, □ removed monument (explain)
Onplaced a
SKETCH OF REFERENCE TIES
4
-N-
6"RED OAK () N80°W N80°E (3 8" RED OAK
18.88 (IV) EAST 3,8
TELIDOS SIGN
\$\frac{\sigma_{\sigma}}{\sigma_{\sigma}}\$
\downarrow
₩ 7" RED OAK
· · · · · · · · · · · · · · · · · · ·
not to scale
Statement of evidence relative to this corner location is on back of page.
1 hereby certify that this document and the data OFFICE OF THE REGISTER OF DEEDS
contained herein was prepared by me or under County of County
my direct supervision. I hereby certify that this document was filed in
the Reg. of Deeds office at 10:45 A. M. on the many day of Many A.D., 1982
Registration No. 11395 Register of Deeds Bulling Bending Register of Deeds Register
I IV COMO 20146AO(* C) LIGHTON LIGHTON LOS TOS TOS TOS TOS TOS TOS TOS TOS TOS T

In 1917, Earl G. Harrington, a US surveyor set a 1"x36" iron pipe with brass cap for CW 1/16 corner from which he made the following BT's. A norway pine N $87\frac{1}{2}$ E 490 LKS and a 6" white oak S $35\frac{1}{2}$ W 41 LKS.

On October 7, 1981, Walter Curo and Paul Johnson find the brass cap monument standing in good condition. Find rotted remains of the 6" white oak bears S 35 W 27 '. Make new BT's as shown on front.