C 1/4 Corner of Section1, Township141, Range30, _5PM. STATE OF MINNESOTA, County of
At the corner location shown on the sketch: Don 10-26-81 found a 1"x36" brass cap monument standing in good condition with one orig. BT standing green, other one rotted left monument as found, lowered monument, removed monument (explain) On placed a SKETCH OF REFERENCE TIES
On 10-26-81 found a 1"x36" brass cap monument standing in good condition with one orig. BT standing green, other one rotted left monument as found, lowered monument, removed monument (explain) On
SKETCH OF REFERENCE TIES
4
IO" WHITE OAK
IO" WHITE OAK
\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
SIGN WEST 580° F
48.59
570°W 12' WHITE OAK
6" WHITE OAK SIGN
16" RED OAK SNAG ORIGINAL B.T.
not to scale Description
Statement of evidence relative to this corner location is on back of page.
I hereby certify that this document and the data OFFICE OF THE REGISTER OF DEEDS
contained herein was prepared by me or under County of County
my direct supervision. ! hereby certify that this document was filed in the Reg. of Deeds office at 10:55 A. M. on the
Wall E. Com 12-8-81 7 day of May A.D., 1982
Registration No. 11395 Register of Deeds Burled Wording
☐ Land Surveyor, ☐ Professional Engineer By MS

In 1917, Earl G. Harrington, a US surveyor set a 1"x36" iron pipe with brass cap for the C 1/4 corner Sec.1 from which he made the following BT's: A 8" red oak S $62\frac{1}{2}$ W 109 LKS and a 8" norway pine S $26\frac{1}{4}$ E 390 LKS.

On October 26, 1981, Walter Curo and Paul Johnson find the brass cap monument standing in good condition. Found remains of a 16" red oak S 62 W 72' and a 22" norway pine standing green S 26 E 257.4'. We make new BT's as shown on the front.