

# CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


SE 1/16 Corner of Section 1, Township 141, Range 30, 5 P.M.

STATE OF MINNESOTA, County of CASS

At the corner location shown on the sketch:

- On 10-16-81 found a broken 1"x36" iron pipe monument with brass cap <sup>DATE</sup> replace it with a 2"x60" iron pipe with brass cap in swamp
  - left monument as found,  lowered monument,  removed monument (explain)
- On \_\_\_\_\_ placed a \_\_\_\_\_  
DATE

### SKETCH OF REFERENCE TIES



not to scale

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Walter E. Leno 12-8-81  
SIGNATURE DATE

Registration No. 11395

- Land Surveyor,  Professional Engineer
- County Surveyor,  County Engineer

262622  
OFFICE OF THE REGISTER OF DEEDS

County of Cass

I hereby certify that this document was filed in the Reg. of Deeds office at 11:00 P.M. on the 7 day of May A.D., 1982

Register of Deeds Dorothy Herdiner

By MS, Deputy

DOCUMENT NO. 262622

In 1917, Earl G. Harrington a US surveyor set a 1"x36 iron pipe with brass cap for the SE 1/16 corner with BT's as follows: A 10" jackpine S 54 E 40 LKS and a 8" oak S 24 $\frac{1}{4}$  W 177 LKS.

On October 10, 1981, Walter Curo and Paul Johnson find the brass cap monument in 2 feet of water and broken in half. We replace it with a 2"x60" iron pipe with brass cap. There is no trace of the original BT's. We make new BT's as shown on front.