CERTIFICATE OF LOCATION OF GOVERNMENT CORNER			
N 1/16 Corner of Section 11 , Township 141 , Range 30 , 5 P.M.  STATE OF MINNESOTA, County of CASS  At the corner location shown on the sketch:			
		On 10-28-81 found a 1"x36" brass cap monument standing in good condition with one orig. BT which checks for bearing and dist.  □ left monument as found, □ lowered monument, □ removed monument (explain)	
		Onplaced a	
SKETCH OF REFERENCE TIES			
9" WHITE OAK  14"RED OAK (DEAD)  ORIGINAL B.T  SIGN  SIGN  EAST  3.5" A SIGN  5" WHITE OAK			
not to scale			
Statement of evidence relative to this corner location is on back of page.			
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.   Alatha Classo 12-8-81  SIGNATURE DATE	OFFICE OF THE REGISTER OF DEEDS  County of		
Registration No. 11395	Register of Deeds <u>Bendulu</u> By <u>M</u> S, Deputy		
<ul><li></li></ul>	DOCUMENT NO. 262637		

In 1917, Earl G. Harrington, a US surveyor set a 1"x36" iron pipe with brass cap for the N 1/16 corner Sec. 11 from which he made the following BT's: A 14" red oak N 20 E 250 LKS and a 8" red oak N 43-1/4 W 133 LKS.

On October 28, 1981, Walter Curo and Paul Johnson find the brass cap standing in good condition. We find a 14" red oak standing, but dead N 43 W 87.8'. The other tree would have been in what is now a pine plantation. We make new BT's as shown on front.