CERTIFICATE OF LOCATION OF GOVERNMENT CORNER Meander Corner on North Corner of Section 3 , Township 138N , Range 31W , 5th P.M. STATE OF MINNESOTA, County of Cass	
At the corner location shown on the sketch:	
內 <u>02/25/81</u> found a <u>2-1/2" capped pipe.</u>	
12 left monument as found, 🗆 lowered monument, 🗆 removed monument (explain)	
Onplaced a	
SKETCH OF REFERENCE TIES	
SECTION 34	
4	Copper nail & disk
Small Lake	In East side of 10"
	Red Oak up 0.5' N20 ^O E 139.12'
SECTION	Copper nail & disk In south side of
33 //	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
/ Low N60°E 113.60'	
Section Corner, Area	
In Lake	T139N
	R Company and S died. T138N
In north side of	
SECTION 348.78	8" Birch up 1'.
	S85°E 73.00'
-	
	Bearings are
l ///	SECTION 3 uncorrected magnetic.
///	* .
Statement of evidence relative to this corner location is on back of page.	
1 hereby certify that this document and the data OFFICE OF THE COUNTY RECORDER	
contained herein was prepared by me or under	County of
my direct supervision.	I hereby certify that this document was filed in
apalina De Dollo al-la.	the Co. Recorders office at 11:20 AM. on the
alphonse Pruelle 9/28/81	25 day of May A.D., 1982
Registration No. <u>//873</u>	County Recorder Bulah Hardrich
श्र्र Land Surveyor, 🗆 Professional Engineer	By M S ,Deputy
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO. 262936

Statement of Evidence:

Meander Corner on North Line of Section 3, Township 138 North, Range 31 West, 5th Principal Meridian. Corner is East of the Northwest Corner of Section 3.

In 1865, during the Original Public Land Survey, wood posts were set south, east, and west of the Northwest Corner of Section 3.

In 1915 Mr. Curo, Cass County Surveyor, set 2-1/2" capped pipes at the three (3) Meander Corner locations. Notes indicate that at the West Meander Corner he found the original post. The South and East Corners are unclear.

In 1940 the CCC (Civilian Conservation Corps) found capped iron pipes at all three locations.

In 1981 the Minnesota Department of Transportation found the capped pipes implace south and east. The west pipe was found lying in the lake.

For details and survey analysis contact the Minnesota Department of Transportation District Surveys Office in Brainerd.