	•		
CERTIFICATE OF LOCATION OF GOVERNMENT CORNER			
SOUTHWEST SIXTEENTH Corner of Section 14 ,Township 144 ,Range 29 , 5th P.M. STATE OF MINNESOTA, County of			
		Onplaced a	
		SKETCH OF REFERENCE TIES	
		1 4	
-N- 			
Nail in			
21" R. Pine			
N 69 W 171.08' Scribed ,	·		
Yes			
```			
	•		
	No. 23 au		
	, Nail in 11".Cedar		
	\$ 30 E 128.05'		
	Scribed		
	BEARINGS ARE APPROXIMATE		
Statement of evidence relative to this corner location is on back of page.			
I hereby certify that this document and the data	OFFICE OF THE COUNTY RECORDER		
contained herein was prepared by me or under	County of		
my direct supervision.	I hereby certify that this document was filed in		
SIGNATURE 9-13-82	the Co. Recorders office at 9:58 A. M. on the  14 day of Sept. A.D., 19 82		
Registration No. 17684	County Recorder Bental Herdriha		
Registration No Professional Engineer	By M. S, Deputy		
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO. 264945		

## Statement of Evidence:

- U.S. General Land Office dependent resurvey established this corner and an iron pipe with a marked brass cap was set to mark the corner. The following bearing trees were marked: 10" Maple S 68 E 22 links and 8" W. Pine N 80 W 35 links.
- U.S. Forest Service technician G. Brama found the corner monumented with a GLO brass cap monument in place in good condition up 12" above ground. The following bearing trees were found: 24" W. Pine stump N 80 W 23.0' and Rotted Maple stump S 68 E-14.5'. Three new bearing trees were marked and are shown on this certificate. Steel sign posts were set 3.1' north and 2.55' south of the corner.
- County Surveyor's Records in the Recorder's Office were checked and no resurvey information was found on this corner.

... _ ... ...

On Sept. 3 I visited the corner and found items as per the 1980 USFS reports. Accepted monument as marking the same location as when set in 1926 based on bearing tree evidence. One bearing tree marked in 1980 was found as a windfall - 23" W. Pine S 82 E 135.88'.