

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


NE 1/16 Corner of Section 11, Township 141, Range 30, 5 P.M.

STATE OF MINNESOTA, County of CASS

At the corner location shown on the sketch:

- On 11-10-81 found a 1"x36" iron pipe with brass cap 1-1/2' below surface of bog with a bend in it
DATE
- left monument as found, lowered monument, removed monument (explain)
- On 11-10-81 placed a 2"x60" iron pipe with brass cap in place of the original monument
DATE

SKETCH OF REFERENCE TIES



not to scale

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Walter E. Cass 12-8-81
SIGNATURE DATE

Registration No. 11395

- Land Surveyor, Professional Engineer
- County Surveyor, County Engineer

265245
 OFFICE OF THE REGISTER OF DEEDS

County of Cass

I hereby certify that this document was filed in the Reg. of Deeds office at 9:10 A.M. on the 29 day of Sept A.D., 19 82

Register of Deeds Dorothy Hendrick County Record.

By MS, Deputy

DOCUMENT NO. 265245

In 1917, Earl G. Harrington a US surveyor set a 1"x36" iron pipe monument with brass cap for the NE 1/16 corner from which he made the following BT's: A 6" poplar N 85-1/2 E 122 LKS and a 6" red oak S 8-1/4 W 266 LKS.

On November 10, 1981, Walter Curo and Paul Johnson found the brass cap monument in the bog standing up 1-1/2 feet below the surface and bent. If we tried to straighten it out, it would break, so we replace it with a 2"x60" iron pipe with a brass cap, check for original BT's, but there is no trace of them due to high water. We make new BT's as shown on front.