CERTIFICATE OF LOCATION OF GOVERNMENT CORNER
A.P. #1 of TR 1589 Corner of Section 31 ,Township 142 ,Range 30 ,5th P.M.
STATE OF MINNESOTA, County ofCASS
At the corner location shown on the sketch:
☑ On 3/12/81 found o GLO brass cap monument as set in 1917.
☑ left monument as found, □ lowered monument, □ removed monument (explain)
Onplaced a
SKETCH OF REFERENCE TIES
\downarrow \downarrow
Nail in law Birch
N 49 W 26.40' Scribed
•
ريخ Nail in
6" R. Oak. S 80 W 17.40'
Scribed
Nail in
9" R. Oak
S 12 W 22.81' Scribed
BEARINGS ARE APPROXIMATE
Statement of evidence relative to this corner location is on back of page.
I hereby certify that this document and the data OFFICE OF THE COUNTY RECORDER
contained herein was prepared by me or under my direct supervision. County of
Thereby dering that his defined in
Nay H. Deven 9-15-82 29 day of Sept. A.D., 1982
Registration No. 17694 County Recorder Durlah Bedulah County Recorder By MS Deputy
I NI LONG SULVEYOR. I I PROJESSIONO ENGINEER I DV 1815

Statement of Evidence:

- U.S. General Land Office dependent resurvey established this corner and an iron pipe with a marked brass cap was set to mark the corner.
- U.S. Forest Service technician W. Olson found the corner monumented with a GLO brass cap monument in good condition up 0.2'. Three new bearing trees were marked and are shown on this certificate. Steel sign posts were set 4.0' north and 4.0' south of the corner. Line was run from the Center ½ corner of Section 30 south through this corner to the CS 1/16 corner of Section 30. The monument fit good with the line and rough-distance measurements also checked good with the 1917 GLO resurvey record.
- 1982 County Surveyor's Records in the Recorder's Office were checked and no resurvey information was found on this corner.
- 1982 On Sept. 9 I visited the corner and found items as per the 1981. USFS reports. The U.S. Forest Service information indicates that the monument was found in the same position as when set in 1917.