and the second of the second o
OF GOVERNMENT CORNER
Township 141, Range 27, 5th P.M.
cap monument as set in 1919.
ed monument,   removed monument (explain)
EFERENCE TIES
I CINCINOE TITO
maan aa
Nail in 8" W. Oak
N 46. E 28.4
Scribed
"· F3
' Yes
3
Nail in
5" W. Oak
N 73.E 22.7'
Scribed
BEARINGS ARE APPROXIMATE
ation is on back of page.
279269 OFFICE OF THE COUNTY RECORDER
County of
I hereby certify that this document was filed in
the Co. Recorders office at 3:51 P. M. on the
S day of D
County Recorder Claudine Kaylor
By MS Deputy
DOCUMENT NO. 279269

Statemer	nt of Evidence:
1919	U.S. General Land Office dependent resurvey established this corner and an iron pipe with a marked brass cap was set to mark the corner. The following bearing trees were marked: 12" W. Oak S 63 W 87 links and 10" W. Oak N 24-45 E 63 links.
1980	U.S. Forest Service technician J. Schoonover found the corner monu- mented with a GLO brass cap monument in good condition up 14". The following bearing trees were found: 15" W. Oak (dead) S 63-W 57.4". No evidence found of the other bearing tree. Three new bearing trees were marked are are shown on this certificate. Corner is on small island surrounded by beaver pond.
1982	County Surveyor's Records in the Recorder's Office were checked and no resurvey information was found on this corner.
1982	Analysis of the above data indicates that the location of this Government corner has been perpetuated. I accepted the monument as marking the corner location as when set in 1919 by the GLO resurvey based on bearing tree evidence.