

# CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTH QUARTER Corner of Section 18, Township 139 N., Range 26 W., 5th P.M.

STATE OF MINNESOTA, County of CASS


At the corner location shown on the sketch:

On 9-16-81 found a 1 1/2" OUTSIDE DIAMETER, CAPPED IRON PIPE, UP 1.4'  
DATE

left monument as found,  lowered monument,  removed monument (explain)

On \_\_\_\_\_ placed a \_\_\_\_\_  
DATE

### SKETCH OF REFERENCE TIES



#### BEARINGS OBSERVED WITH COMPASS

Statement of evidence relative to this corner location is on back of page.

J. B. M. 12-3-84  
A-720

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Bert R. Evland 12-14-84  
SIGNATURE DATE

Registration No. 10516

- Land Surveyor,  Professional Engineer  
 County Surveyor,  County Engineer

279865  
 OFFICE OF THE COUNTY RECORDER

County of Cass

I hereby certify that this document was filed in the Co. Recorders office at 10:15 A.M. on the 9 day of January A.D., 1985

County Recorder Claudia Kayler  
 By MS, Deputy

DOCUMENT NO. 279865

North Quarter Section 18, Township 139 North, Range 26 West

This corner was originally established by the U. S. General Land Office in 1863. The government notes show corner marked with a wood post with the following bearing trees marked:

9" Yellow Pine, North, 22 links (14.52 feet)  
10" White Pine, South, 26 links (17.16 feet)

In September 1981, the DNR Bureau of Engineering contacted the following Registered Land Surveyors for corner information:

Walt Curo, Hackensack  
Wally Buckler, Crosby

In February 1983, the DNR Bureau of Engineering received the following information from the Cass County Surveyor's Office:

Civilian Conservation Corps notes received from Washburn Lake Forestry Station, Book 3, Page 41 contains a survey made in 1936. Survey shows an iron pipe at corner but does not state if it was found or set.

On September 16, 1981, the DNR Bureau of Engineering traversed to the area of the corner and found an 1½ inch outside diameter iron pipe with a 2 inch outside diameter scribed cap. Searched for but did not find the wood post or bearing trees marked by the GLO.

Accept the iron pipe as the location of the original government corner.

Traverse information is available from the DNR Bureau of Engineering.