CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
between Neander #28 Corner xxf Section 7 & 8 Township 141N Range 31W , 5th P.M.	
STATE OF MINNESOTA, County of	
At the corner location shown on the sketch:	
□ On found a	
☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)	
On 1-3-85 placed a 2½ inch (0.D.) x 5 foot long iron pipe with a 3 inch diameter brass cap, stamped as shown, up 1.0 feet.	
Declination; 6° East SKETCH OF REFERENCE TIES NOT TO SCALE TEN LAVE	
TEN	LAKE
- N -	
8 foot steel post with F.S. Sign 54-9 attached, N10°W, 3.39 feet	White Oak 8 inch N21°E, 9.37 feet
\$7 \$8 \$7 \$8 \$7 \$8 \$7 \$8	
Ash 7 inch S82°W, 36.21 feet	
Ash 12 inch S7°W, 7.79 feet	
NOTE: All bearing trees are painted red and marked with F.S. sign No. 54-3 with a nail in base, double blazed and scribed.	
Statement of evidence relative to this corner location is on back of page.	
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. William D. Clermon 2-1-85	OFFICE OF COUNTY RECORDER County of
Registration No. <u>6807</u>	County Recorder Cloudine Kaylon By M S , Deputy
□ County Surveyor, □ County Engineer	DOCUMENT NO. 280562

Statement of Evidence: Meander Corner between Sections 7 & 8, Township 141 North, Range 31 West, 5th Principal Meridian. South side of Ten Lake.

P.H. Conger, U.S. Deputy Surveyor, set a post for this Meander Corner in his subdivision of the Township between August 5, 1873 and August 30, 1873. As references he scribed:

Elm 4 inch S72°E 9 links (5.94 feet) Norway Pine 14 inch S40°W 72 links (47.52 feet)

- J. Curo, Cass County Surveyor, did not find any evidence of corner during his survey of Section 7. He did set a Witness Corner to his position for the Quarter Corner, 176 feet South. A 2½ inch by 47 inch capped iron pipe was set according to County Resurvey Plat "E 51".
- H. Curo, Cass County Surveyor, found no evidence of the Meander Corner. He did find iron monument set in 1915 for a Witness Corner to the Quarter Corner and made references as follows:

White Oak 4 inch S53°46'E 28.25 feet Elm 9 inch S3°32'E 27.3 feet Elm 7 inch S46°33'W 46.5 feet

- 1962 U.S.F.S. Corner Restoration notes indicate iron monument set as Witness Corner to Quarter Corner found with 1959 BT's all in good condition. A 6 foot steel post was added as a reference.

 6 foot steel post N21½°W 4.25 feet
- Kelly M. Booge, under F.S. Contract No. 53-6392-4-00996, made a thorough search for physical evidence of this corner on September 12, none was found. He did fine the iron monument set by Curo for a Witness Corner to the Quarter Corner. He returned on January 3, 1985 and searched for evidence on the corner position but found no further evidence. He then set a monument in the lost position, with ties as shown on the sketch, proportioned distance and on a straight line between adjacent corners.

Kelly M. Booge is an employee of Okerman Surveying, Inc.