CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
East 1/4 Corner of Section 31 ,Township 144N ,Range 25W , 5th P.M.	
STATE OF MINNESOTA, County of	
At the corner location shown on the sketch:	
□ On found a	
☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)	
X On 9-26-1984 placed a 2 1/2" (O.D.) by 5 feet long galvinized iron pipe with 3" brass cap stamped as shown Up 1.5 feet	
SKETCH OF REFERENCE TIES Not to Scale 7"CEDER 9"CEDER 132.73" 1344 R25W VA Sal S32 1984 RLS 9235 Note: Trees are blazed & scribed with B.T. tag. Distances shown are to a 200 nail in notch painted red on side of tree.	
Statement of evidence relative to this corner location is on back of page.	
Registration No. 9235 Land Surveyor, County Engineer I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. 3/29/85 Registration No. 9235 County Surveyor, County Engineer	OFFICE OF THE COUNTY RECORDER County of

Statement of Evidence:

X5

This corner was originally established in April, 1876, by B.C. Baldwin, Deputy Surveyor. The field notes of that survey are filed in the office of the Secretary of State, St. Paul, Minnesota. Mr. Baldwin's notes state that a post was set to mark the corner and referenced by the following:

A 8" Tamarck that bears N43°E a distance of 14 links [9.24 feet] A 4" Spruce that bears N68°W a distance of 15 links [9.90 feet]

On July 16, 1984, personnel from Advance Surveying & Engineering Co. made a thorough search for this corner and the above mentioned references but to no avail. However we do find 2 Tamaracks that the U.S.F.S. has cut open looking for original Bearing Trees. No evidence found.

On September 26, 1984, an additional search was made by Advance prior to reestablishing this corner at its "lost" position half way and on line between adjacent Section corners.