


CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

East Quarter Corner of Section 27, Township 142, Range 26, 5th P.M.
 STATE OF MINNESOTA, County of Cass

At the corner location shown on the sketch:

- On 4-29-86 found a 2"x60" galv. iron pipe with brass cap
 with a ^{DATE} 1.5" pipe along side in a swamp 5' from w. edge
 - left monument as found, lowered monument, removed monument (explain)
- On _____ placed a _____
 DATE _____

Not to scale. SKETCH OF REFERENCE TIES



All measurements are to spks. in side of the tree, trees are double blazed and scribed and painted red with USFS 54-3 bearing tree tag.

Statement of evidence relative to this corner location is on back of page. 291467

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Walter P. Larsen 9-2-86
 SIGNATURE DATE

Registration No. 11395
 Land Surveyor, Professional Engineer
 County Surveyor, County Engineer

OFFICE OF THE REGISTER OF DEEDS
 County of Cass

I hereby certify that this document was filed in the Reg. of Deeds office at 3:27 P.M. on the 5 day of Sept A.D. 1986

Register of Deeds Claudine Kayler
 By MS, Deputy

DOCUMENT NO. 291467

STATEMENT OF EVIDENCE East Quarter Corner Section 27, T 142 N,
R. 26 W., 5th P.M.

- 1872 U.S. General Land Office survey set a wood post for this corner and marked the following bearing trees: 12" Aspen S 20 W 18 lks., 10" Aspen East 11 lks.
- 1921 James Flynn County Surveyor set 1½" x 44" pipe by proportion. County Book "C", Page 416.
- 1963 Bill Okerman, U.S. Forest Service found the 2" pipe set by Flynn in 1921. Bill then set a 2" x 60" galv. iron pipe filled with concrete with a brass cap, marked the following BT's and filed a Certificate of Location of Government Corner. 12" Tamarack N 83 E 62.5', 23" Red Pine N 13 E 155.0', 8" Oak S 71 W 29.3', 4" x 4" x 60" Cedar post South 2.25' with signs 54-2 & 54-4.
- 1982 Walter E. Curo under contract with the USFS found this monument standing in good condition and set a 8' steel post with signs 3' East.
- 1986 Walter E. Curo under contract with the USFS found this monument standing in good condition. I file this certificate to update the 1963 Okerman certificate.