

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER



southeast Corner of Section 30, Township 143, Range 27, 5th P.M.

STATE OF MINNESOTA, County of Cass

At the corner location shown on the sketch:

- On 9-8-86 found a 2"x36" iron pipe with brass cap flush with surface of the bog beside a rotted wood post
- left monument as found, lowered monument, removed monument (explain)
- On _____ placed a _____

Not to scale. SKETCH OF REFERENCE TIES



5' steel sign posts 2.6' east and 4.4 west

no trees available.

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Walter E. Carr 9-12-86
SIGNATURE DATE

Registration No. 11395

- Land Surveyor, Professional Engineer
- County Surveyor, County Engineer

291628
OFFICE OF THE REGISTER OF DEEDS
County of Cass

I hereby certify that this document was filed in the Reg. of Deeds office at 9:10 A.M. on the 15 day of Sept. A.D., 1986

Register of Deeds Claudia Kogler
By ms, Deputy

DOCUMENT NO. 291628

STATEMENT OF EVIDENCE

Southeast Corner of Section 30, Township 143
north, Range 27 West of the 5th Principal Meridian

1873 GLO set a wood post to mark this corner and marked the following BT'S

7" Tamarack	North 6 East	125 Lks (82.50 feet)
4" Tamarack	South 6 East	450 Lks (297.00 feet)
5" Tamarack	South 8 West	480 Lks (316.80 feet)
6" Tamarack	North 62 West	200 Lks (132.00 feet)

1928 GLO resurvey set a 2"x36" iron pipe with brass cap and a cedar post along side of it. No trees available.

1970 Curt Krouse of the USFS located the iron with the cedar post. He set 5' steel sign posts 2.6' east and 4.4' west.

1986 Walter E. Curo found the 2" iron pipe with brass cap and rotted post along side of it. Both steel sign posts are still standing. This pipe is flush with surface of the bog.