CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
NORTHEAST Corner of Section 7 ,Township 140 ,Range 26 ,5th P.M.	
STATE OF MINNESOTA, County ofCASS	
At the corner location shown on the sketch:	
On 6-24-85 found o 2" capped iron pipe monument down 4" in road bed.	
left monument as found, lowered monument, removed monument (explain)	
On 6-24-85 placed a county cast iron monument over found pipe down	
SKETCH OF REFERENCE TIES	
14	
-N-	
4	
Spk in 12" TAM S 80°W 90'	
Spk in 18" ★ TAM S 30 W 28.62'	
	Spk in 5" TAM S 30°E 76.33"
	BEARINGS ARE APPROXIMATE
Statement of evidence relative to this corner location is on back of page. 295281	
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. Aug H. Aleven 2/21/87	OFFICE OF THE COUNTY RECORDER County of
Registration No. 12684	County Recorder Clandine Kaylor
🕱 Land Surveyor, 🗆 Professional Engineer	By MS Beputy DOCUMENT NO. 295281
□ County Surveyor, □ County Engineer	DOCUMENT NO. 295281

Mn/DOT 2105 (4-77)

Statement of Evidence:

- 1871 U.S. General Land Office survey (set wood post) for this corner and marked the following bearing trees: 3" Tam N 14° W 12 links, 5" Tam N 7° E 13 links, and 4" Tam S 34° E 23 links.
- 1922 Plat of OAK LAWN BEACH was surveyed by John M. Green. Plat shows this corner as an original government corner and monumented with an iron monument.

1937

- CCC notes at MN/DNR Washburn Lake Forestry station show a found iron pipe buried under road with ties: 5" B1. Spruce N 48½ E 25.4' (1937-24.5') scribed, 6" B1. Spruce S 39½ E 35'(1937-34.6') scribed, 6" B1. Spruce S 21° W 39.5' (1937-40') scribed and 6" Spruce on ground N 69½ W 37' scribed.
- 1979 Found 1" iron pipe down 0.1' in N-S road. Pipe had been set by Anthony Kerick, RLS over found iron monument. We found partial remains of stumps with scribing visable: S 25° W 36'- and N 53° E 28'-.
- 1983 We revisited corner and found that pipe set by Kerick has been torn out by road grader.
- We dug down in road 4' and found top of 2" capped iron monument. This was identified a the type of standard county monument set by Green and other county surveyors in the early 1900's. A county cast iron monument was set over the found pipe and ties taken as shown on this certificate. Corner is 6 feet west of approximate center line of town road and 14 feet north of power line crossing.