



Statement of Evidence: East one-sixteenth Corner, North Line, Section 1, T.141 N., R.28 W., 5th P.M.

- 1919 US General Land Office dependent resurvey established this corner by setting a 1"x36" I.P. with marked brass cap and marked the following bearing trees: 8" Tam. N  $49\frac{1}{2}^{\circ}$ E. 41.1ks., 5" Tam. S  $31\frac{3}{4}^{\circ}$ E. 22.1ks.
- 1973 US Forest Service personnel found evidence of the 1919 GLO survey. No new monument was set, as the GLO monument is in good condition. New bearings marked: 14" Cedar N  $57^{\circ}$ W 42.90', 10" Tam. S  $78^{\circ}$ E 24.70', 6" Tam. S  $32^{\circ}$ W 13.50'. All trees scribed. William Okerman filed CERTIFICATE OF LOCATION OF GOVERNMENT CORNER.
- 1987 Walt Curo, under contract with the US Forest Service, found the GLO brass cap monument. He marked the following bearing trees: 15" Balsam EAST 24.90', 12" Balsam S  $22^{\circ}$ W 13.30', 8" Basswood N  $78^{\circ}$ W 25.65', 20" Cedar N  $57^{\circ}$ W 42.9'. He files this certificate to update the 1973 certificate.