CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
S-N 1/64 Corner of Section 1 ,Township 141 N. , Range 28 W. , 5th P.M.	
STATE OF MINNESOTA, County of	
At the corner location shown on the sketch:	
On 7/15/87 found a GLO brass cap monument near surface, lowered to 10" below surface left monument as found, Di lowered monument, I removed monument (explain)	
□ Onplaced a	
SKETCH OF REFERENCE TIES	
Not to scale	
24" Red Oak S 81°W 57.25' Trees double blazed, scribed, painted red and Measurement taken to nail in side of tree.	
Statement of evidence relative to this corner location is on back of page. 301671	
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. White and Surveyor	OFFICE OF THE COUNTY RECORDER County of
	DOCUMENT NO. 301471

S-N 1/64 Corner on East Line Section 1,T.141 N.,R.28 W., 5th Statement of Evidence: (A.P. #1 Tract 1532 & A.P. #4 Tract 1533). US GEneral Land Office dependent resurvey established this 1918 corner with a 1"x36" I.P. with marked brass cap. Corner falls in road-set 36" in ground. No bearing trees marked. 1972 US Forest Service personnel found remains of 1918 GLO survely and information documented in Forest Service record. No. new monument set, as GLO monument was in good condition. The follwoing bearings were marked: 8" W.Oak S 70°W 81.40', 5" W.Oak S.47°E 37.80',6"W.Oak S.45°W 115.40', all blazed and scribed. 4"x4" Cedar Post WEST 15.10'. Willaim Okerman filed CERTIFICATE OF LOCATION OF GOVERNMENT CORNER. 1987 Walt Curo, under Forest Service contract, found GLO brass cap monument at surface of road and 1972 BT SE. Lowered monu-

ment 10" and marked new BT's. 14" Red Oak N 89°E 33.55', 6" Burr Oak N 23°E 42.10',24" Red Oak S 81°W 57.25'. He files this certificate to update the 1972 certificate.

1.