

# CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


THE EAST QUARTER Corner of Section 14, Township 139, Range 29, 5TH P.M.

STATE OF MINNESOTA, County of CASS

At the corner location shown on the sketch:

- On 3/10/88 found a 1 1/4" IRON PIPE PROTRUDING 3' ABOVE GROUND
- left monument as found,  lowered monument,  removed monument (explain)
- On \_\_\_\_\_ placed a \_\_\_\_\_

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page 306660

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Don R. Rasmussen May 17, 1988  
Signature Date

Registration No. 16102  
 Land Surveyor,  Professional Engineer  
 County Surveyor,  County Engineer

OFFICE OF THE COUNTY RECORDER  
County of Cass

I hereby certify that this document was filed in the County Recorders office at 4:16 P.M. on the 18 day of Aug. A.D., 1988.

County Recorder Claudia Kayler  
By ms, Deputy  
DOCUMENT NO. 306660

Statement of Evidence:

**EAST QUARTER CORNER SECTION 14, T139N, R29W:**

- 1865 - The original government survey was run and a post was set to mark this corner.
- 1928 - John Curo, Cass County Surveyor, surveyed and subdivided Section 14. He recovered the section corners north and south of this location but found no evidence of the original government survey for this corner. He established this corner on line between the section corners found north and south and at proportionate measurement with the original government survey. This information is from Curo's field Book 156, Pages 57, 68-72.
- 1952 - Harold Curo, Mn. RLS #3417, used John Curo's 1928 field notes to make the plat of SHADYWOOD SHORES.
- 1978 - William Spain, Mn. RLS #2003, surveyed and subdivided Section 14. He found this corner in place. His measurements to other corners recovered in Section 14 checked closely with John Curo's 1928 measurements. This information is from Spain's certificate of survey dated January 31, 1978.
- 1988 - A Widseth Smith Nolting survey crew recovered a 1-1/4" pipe protruding above ground 3 feet. Measurements made from this pipe along the east line of Section 14 to the section corners found north and south checked closely with Curo's 1928 measurements and Spain's 1978 measurements. This monument was accepted as the quarter corner.