


CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

THE NORTHEAST Corner of Section 13, Township 139, Range 29, 5th. P.M.

STATE OF MINNESOTA, County of CASS

At the corner location shown on the sketch:

- On 3/9/88 found a 2 1/2" X 36" CAPPED IRON PIPE
- left monument as found, lowered monument, removed monument (explain)
- On _____ placed a _____



Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Donna R. Rasmussen May 17, 1988
 Signature Date

Registration No. 16102

- Land Surveyor, Professional Engineer
- County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER
 County of Cass

I hereby certify that this document was filed in the County Recorders office at 4:17 P. M. on the 18 day of August, A.D., 1988.

County Recorder Clouetine Koyler
 By MS, Deputy

DOCUMENT NO. 306661

Statement of Evidence:

NORTHEAST CORNER SECTION 13, T139N, R29W

- 1865 - The original government survey was run and a post was set to mark this corner.
- June 21, 1911 - John Curo, Cass County Surveyor recovered "the old stake and the roots of the old government bearing trees which check out correct". He set a new stake for this corner. He also found the original government meander corner at the government distance north of this section corner. This information is from County survey records, Book A, Pages 364-368.
- September 2, 1911 - Charles M. Pidgeon, U.S. Surveyor, surveyed an island in Hay Lake for the United States General Land Office. Mr. Pidgeon commenced his survey at this section corner where he recovered a badly charred 3"x3" oak post protruding 36" above ground with the section numbers marked on it. His notes state that the bearing trees were destroyed by fire and that he could find no evidence of the meander corner to the north. This information is from Pidgeon's field notes.
- 1919 - Ben F. Clark, Surveyor, surveyed the township line between Township 139 North, Range 29 West, and Township 139 North and Range 28 West and several sections to the east of this line. For this corner he recovered "a dry oak post with the marks cut in with a knife." He found no evidence of the original bearing trees or the meander corner to the north. He replaced this post with a 2'1/2" X 36" iron pipe. No new bearing trees were established. This information is from County survey records, Book C, Pages 327-333.
- 1921 - Ben F. Clark made two (2) plats of his survey from the field work done in 1919. These plats are filed in the Cass County Courthouse.
- 1988 - A Widseth Smith Nolting survey crew recovered an iron pipe for this corner which matches identically with the description of the monument set by Clark in 1919. Measurements made along the township line to other corners which were recovered matched closely to Clark's 1919 measurement. The shoreline of Hay Lake to the west and to the north and the shoreline of the island surveyed by Pidgeon in 1911 were found to match closely to the meanders run by the original government surveys in relation to this iron pipe. This iron pipe was accepted as the section corner and new bearing trees were established.