


CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

THE NORTHEAST Corner of Section 14, Township 139, Range 29, 5TH P.M.
 STATE OF MINNESOTA, County of CASS

At the corner location shown on the sketch:

- On 10/13/87 found a 2 1/2" IRON PIPE MONUMENT PROTRUDING 18" ABOVE GROUND
STAMPED "2003" ON ITS SIDE
- left monument as found, lowered monument, removed monument (explain)
- On _____ placed a _____

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page. 306662

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Don R. Raemus May 17, 1988
 Signature Date

Registration No. 16102
 Land Surveyor, Professional Engineer
 County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER
 County of Cass

I hereby certify that this document was filed in the County Recorders office at 4:18 P. M. on the 18 day of August A.D., 1988.

County Recorder Claudia Kayler
 By MJ, Deputy
 DOCUMENT NO. 306662

Statement of Evidence:

NORTHEAST CORNER SECTION 14, T139N, R29W:

- 1865 - The original government survey was run and a post was set to mark this corner.
- 1928 - John Curo, Cass County Surveyor, surveyed and subdivided Section 14. He recovered one of the original government bearing tree stumps and reset a stake for this corner from the stump. This information is from Curo's field Book 156, Pages 43-45.
- 1952 - Harold Curo, Mn. RLS #3417, used John Curo's 1928 field notes to make the plat of SHADYWOOD SHORES.
- 1978 - William Spain, Mn. RLS #2003, surveyed and subdivided Section 14. He found this corner in place. His measurements to other corners recovered in Section 14 checked closely with John Curo's 1928 measurement. This information is from Spain's certificate of survey dated January 31, 1978.
- 1988 - A Widseth Smith Nolting survey crew recovered a 2 1/2" pipe with William Spain's registration number stamped on it. Several bearing trees of unknown origin (probably Spain's) were found witnessing this corner. A rotted pine stump which fit the location of Curo's recovered original BT stump was also found. Measurements made along the east line of Section 14 matched closely with Curo's and Spain's previous measurements. This monument was accepted as the section corner.