

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

North Quarter Corner of Section 17, Township 141 N, Range 30 W, 5th P.M.

STATE OF MINNESOTA, County of Cass

At the corner location shown on the sketch: Latitude: 47° 02' 16.95055"
 Longitude: 94° 30' 09.43940"



On 7/20/88 found a 1/2 inch rerod.
DATE

left monument as found, lowered monument, removed monument (explain)

On 7/20/88 placed a 2 inch by 24 inch Iron Monument with a Brass
DATE
Cap at rerod position.

Magnetic Decl: 5° East
 Not to Scale

SKETCH OF REFERENCE TIES All distances are horizontal to nail in side of tree.



Monument is located 9" Norway Pine
3 and 1/2 feet North S 4 E 64.14'
 of Centerline of
 Forest Service Road
 Number 3781.

8 foot sign post South 20.0 feet.
 All trees are painted with red enamel
 and marked with a 54-3 (Bearing Tree) tag.

Monument Stamped

T 141 N R 30 W

1/4 S 8
S 17
 1988

RLS No. 17008

Statement of evidence relative to this corner location is on back of page.

309834

I hereby certify that this survey, plan or report was prepared by me or under my direct supervision and that I am a duly Registered Land Surveyor under the laws of the State of Minnesota.

David S. Landecker
 David S. Landecker
 Date 12-15-88 Registration No. 17008

OFFICE OF THE COUNTY RECORDER

County of Cass

I hereby certify that this document was filed in the Co. Recorders office at 9:45 A. M. on the 12 day of January A.D., 1989

County Recorder Claudine Koyler

By MS, Deputy

DOCUMENT NO. 309834

Statement of Evidence:

North Quarter Corner Section 17, Township 141
North, Range 30 West, Cass County, Minnesota

J-7 141-30
Bk.5 Pg.10

1873 P. H. Conger, U.S. Deputy Surveyor, originally established this corner position while subdividing Township 141 North, Range 30 West. The notes indicate a wood post was set to mark the corner position and the following witnesses: a 10 inch Poplar South 21 degrees East a distance of 53 links; and a 8 inch Birch North 1 degree East a distance of 72 links.

1912 County Surveyor's Record Book C page 56 shows survey by M.A. Kemp. He found a 4 inch x 4 inch x 36 inch post that checks with roots of the original bearing trees.

1917 U.S. General Land Office dependant resurvey established this corner proportionally between the Northeast and the Northwest Corners of said Section 17. A 1 inch by 36 inch iron pipe with a marked brass cap was set to mark this corner. The following bearing trees were marked: a 6 inch Jack Pine South 31 and 1/2 degrees East a distance of 242 links; and a 10 inch Red Oak North 75 and 1/2 degrees West a distance of 140 links.

1979 U.S. Forest Service technicians Hayes and Krause found the corner monumented with a bent brass cap monument, they straightened monument. The following bearing trees were found: 1917 Jack Pine is now a 21 inch Norway Pine at bearing and distance. 3 new bearing trees were marked and are shown on this certificate.

1981 U.S. Forest Service records show the following: Monument removed because it is in new road right of way.

1986 U.S. Forest Service crews set an aerial target over this corner position for determination of coordinate values through the use of GPS on the Chippewa South Boundary Project Cadastral Survey U.S. Project Number 53-6392-8-219. This target allowed for the search and location of this corner.

1988 on July 20 a Landecker-Stevenson & Associates crew searched for the corner using USFS rerod set for target center to determine search area. The following information was found: 1917 GLO bearing tree now a 22 inch Norway Pine South 32 degrees East a distance of 159.70 feet and all three 1979 U.S. Forest Service bearing trees.

1988 on July 20 a Landecker-Stevenson & Associates crew set a 2 inch x 24 inch iron pipe (using existing bearing trees), with marked brass cap, set down 9 inches in road, 3 and 1/2 feet north of centerline of Forest Service Road 3781. The 1917 GLO and 1979 USFS bearing trees are shown on front of this certificate, sign post is in place as shown.