

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

EAST QUARTER Corner of Section 21, Township 141 N, Range 29 W, 5th P.M.

STATE OF MINNESOTA, County of CASS

At the corner location shown on the sketch: Latitude: 47° 00' 59.794"
 Longitude: 94° 20' 58.403"


On 6/15/88 found a 1" iron monument with a brass cap
DATE

left monument as found, lowered monument, removed monument (explain)

On _____ placed a _____
DATE

Magnetic Decl: 5° East SKETCH OF REFERENCE TIES
 Not to Scale

All distances are horizontal to nail in side of tree



Monument is located 100' more or less north of trail number 2312A, cutover westerly, line to standard northerly. 8' sign post north 4.0' 8' sign post east 5.0'

All trees are painted with red enamel and marked with a 54-3 (Bearing Tree) tag.

Monument Stamped

S 21 ^{1/4} S 22
 1918

Statement of evidence relative to this corner location is on back of page. 310667

I hereby certify that this survey, plan or report was prepared by me or under my direct supervision and that I am a duly Registered Land Surveyor under the laws of the State of Minnesota.

David S. Landecker
 David S. Landecker

Date 2/28/89 Registration No. 17008

OFFICE OF THE COUNTY RECORDER
 County of Cass

I hereby certify that this document was filed in the Co. Recorders office at 2:25 P.M. on the 1 day of March A.D., 1989

County Recorder Claudia Kayler
 By MS Deputy

DOCUMENT NO. 310667

Statement of Evidence:

East Quarter Corner Section 21, Township 141
North, Range 29 West, Cass County, Minnesota

P-13 141-29
Bk.4 Pg.34

1873 P. H. Conger, U.S. Deputy Surveyor, originally established this corner position while subdividing Township 141 North, Range 29 West. The notes indicate a wood post was set to mark the corner position and the following witnesses: a 10 inch Black Oak North 56 degrees East a distance of 57 links; and a 26 inch Yellow Pine South 31 degrees West a distance of 23 links.

1918 U.S. General Land Office dependant resurvey reestablished this corner proportionally between the Northeast and Southeast corners of said Section 21. An iron pipe with a marked brass cap was set to mark the corner. The following bearing tree was marked: a 7 inch White Pine South 41 degrees 15 minutes East a distance of 131 links.

1980 U.S. Forest Service technician Olson found the corner monumented with a brass cap monument. The following new bearing trees were marked: a 6 inch Jack Pine North 34 degrees East a distance of 35.05 feet; a 15 inch Norway Pine South 84 degrees East a distance of 36.15 feet; and an 8 inch Birch North 20 degrees West a distance of 19.58 feet.

1982 U.S. Forest Service records show the following: Curt Krause, technician, searched for 1918 Pine bearing tree. No positive evidence was found. Monument appears to be undisturbed.

1982 Gary Stevenson, Registered Land Surveyor Number 12684 found items as per 1980 USFS report. He filed a corner certificate using the 1980 USFS information.

1986 U.S. Forest Service crews set an aerial target over this corner position for determination of coordinate values through the use of GPS on the Chippewa South Boundary Project Cadastral Survey U.S. Project Number 53-6392-8-219. This target allowed for the search and location of this corner.

1988 on June 15 a Landecker-Stevenson & Associates crew visited the corner and found the following evidence: GLO brass cap monument in good condition, 1980 bearing tree now a 16 inch Norway Pine South 84 degrees East a distance of 36.15 feet. New bearings trees were marked and steel sign post set as shown on front of this certificate.