CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER
East Quarter Corner of Section 29	.Township141 N ,Range 30 W , 5tb P.M.
STATE OF MINNESOTA, County ofCass	
At the corner location shown on the sketch:	Latitude: 47° 00' 05.011" Longitude: 94° 29' 30.462"
On found a	
☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)	
M On 10/7/88 placed a 2 inch by	48 inch iron pipe with brass cap.
Magnetic Decl: 5° East SKETCH OF REFERENCE TIES All distances are horizontal to nail in side of tree.	
20" Norway Pir ZN 77 W 12.47'	10" Red Oak N 79 E 39.57'
6" Red Oak S 35 W 5.57'	
Monument is located 160 feet, more or less, westerly of Pine plantation and 400 feet, more or less, westerly of Forest Service Trail Number 3772. 8' Sign post North 5.0' All trees are painted with red ename marked with a 54-3 (Bearing Tree) ta	
Statement of evidence relative to this corner location is on back of page. 310871	
I hereby certify that this survey, plan or report was prepared by me or under my direct supervision and that I am a duly Registered Land Surveyor under the laws of the State of Mingesota. Manual David S. Landecker 17008	OFFICE OF THE COUNTY RECORDER County of I hereby certify that this document was filed in the Co. Recorders office at 2:30 PM. on the 14 day of March A.D., 1989 County Recorder Claredic Kaylor By 15

East Quarter Corner Section 29, Township 141 North, Range 30 West, Cass County, Minnesota

> T-9 141-30 Bk.5 Pg.52

- 1873 P. H. Conger, U.S. Deputy Surveyor, originally established this corner position while subdividing Township 141 North, Range 30 West. The notes indicate a wood post was set to mark the corner position and the following witnesses: a 10 inch Red Oak South 4 degrees East a distance of 16 links; and a 12 inch Yellow Pine North 68 degrees West a distance of 7 links.
- 1964 U.S. Forest Service notes show the following: technician Ekstrom searched for the corner, but found no evidence.
- 1986 U.S. Forest Service crews set an aerial target in the vicinity of this corner for the search and establishment of the true corner position. The target having coordinate values through the use of GPS on the Chippewa South Boundary Project Cadastral Survey U.S. Project Number 53-6392-8-219. This target allowed for the search and location of this corner.
- 1988 on September 21 a Landecker-Stevenson & Associates crew searched for the corner. The following information was found and noted: some pine stumps badly burned, all to small to be original bearing trees. No evidence of original post or accessories.
- 1988 on October 7 a Landecker-Stevenson & Associates crew set a 2 inch by 48 inch iron pipe with brass cap and plastic base with magnet at the lost, single proportion position between the Northeast and Southeast Corners of Section 29. New bearing trees were marked and steel sign post set as noted on front of this certificate.