CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
Number 9 Meander Corner of Section 35 ,Township 141 N, Runge 29 W , 5th P.M.	
STATE OF MINNESOTA, County of	
At the corner location shown on the sketch:	Latitude: 46° 58' 46.014" Longitude: 94° 19' 15.545"
On 10/25/88 found a both original Pine bearing tree stumps	
☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)	
On 3/17/89 placed a 2 inch by 48 inch iron pipe with brass cap and plastic base with magnet.	
Magnetic Decl: 5° East SKETCH OF REFERENCE TIES All distances are horizontal to nail in side of tree.	
-N- Barnum	N 66 E 41.64'
Lake /	Original Pine bearing tree stump N 72 E 30.4'
	-O1½" pipe Easterly 2.3'
	Original Pine bearing tree
Monument is located 6' Easterly of waters	
edge of Barnum Lake.	
8' steel sign post East 2.1' 16" Norway Pine South 45.28'	
red enamel and marked with	
a 54-3 (bearing tree) tag.  Monument Stamped R29W	
	MC /S35 T141N
	\S3 T140N 1989
	RLS 17008
Statement of evidence relative to this corner location is on back of page. $31/953$	
l hereby certify that this survey, plan or	OFFICE OF THE COUNTY RECORDER
report was prepared by me or under my direct supervision and that I am a duly	County of
Registered Land Surveyor under the laws	I hereby certify that this document was filed in the Co. Recorders office at 1012.5. M. on the
of the State of Mignesota.	9 day of May A.D., 19 &9
_ 1/ Mud & Tudleln_	County Recorder Claudine Kayler
David S. Landecker  Date 5-1-89 Registration No. 17008	DOCUMENT NO. 3119-53
Dute 0-1-01 Registration No +7008	DOCUMENT NO. 311953

## Statement of Evidence:

Meander Corner Number 9 Section 35, Township 141 North, Range 29 West, Cass County, Minnesota

Z17-18 141-29 Bk.6 Pg.34

1863 Johnson and Thornton, U.S. Deputy Surveyors, originally established this corner position while running the 10th Standard Parallel. The notes indicate a wood post was set to mark the corner position and the following witnesses: a 14 inch Yellow Pine North 72 degrees East a distance of 46 links; and a 15 inch Yelow Pine South 44 degrees East a distance of 26 links.

1915 County Surveyor's Record Book C page 235 show survey by Frank Donner. He found both Government bearing tree stumps; set a 4 by 4 by 36 inch Birch post.

1986 U.S. Forest Service records show the following: Forest Service technicians and County survey technician find both original bearing tree stumps, Northeast has blazing and scribing.

1988 a Landecker-Stevenson & Associates crew visited the corner and found the following evidence: both 1863 bearing tree stumps, Northeast has blaze and scribing, set rebar at original bearing and distance from which a 1 and 1/4 inch iron pipe is Easterly 2.3 feet.

1989 on March 17 a Landecker-Stevenson & Associates crew set a 2 inch by 48 inch iron pipe with brass cap, plastic base and magnet from the stumps of both original bearing trees. New bearing trees were marked as shown and a steel sign post was set as noted on front of this certificate.