


CERTIFICATE OF LOCATION OF GOVERNMENT CORNERStandard Southeast Corner of Section 34, Township 141 N, Range 28 W, 5th P.M.STATE OF MINNESOTA, County of CassAt the corner location shown on the sketch: Latitude: 46° 58' 40.994"
Longitude: 94° 11' 50.008" On _____ found a _____
DATE left monument as found, lowered monument, removed monument (explain) On 5/4/89 placed a 2 inch by 24 inch iron pipe with brass cap
DATE and plastic base with magnet.Magnetic Decl: 5° East SKETCH OF REFERENCE TIES
Not to Scale

All distances are horizontal to nail in side of tree.

Monument is located
11.7' Southerly of center
line of County Road Number
7 at edge of bituminous.
8' steel sign post North 61.7'Monument Stamped
R28W
SC
S34 | S35 T141N
T140N1989
RLS 17008All trees are painted with red enamel and
marked with a 54-3 (bearing tree) tag.

Statement of evidence relative to this corner location is on back of page.

312359I hereby certify that this survey, plan or
report was prepared by me or under my
direct supervision and that I am a duly
Registered Land Surveyor under the laws
of the State of Minnesota.

David S. Landecker

Date 5-24-89 Registration No. 17008

OFFICE OF THE COUNTY RECORDER

County of CassI hereby certify that this document was filed in
the Co. Recorders office at 9:55 A .M. on the
25 day of May A.D., 19 89County Recorder Claudia KaylerBy MS, DeputyDOCUMENT NO. 312359

Statement of Evidence: Standard Southeast Corner Section 34, Township 141 North, Range 28 West, Cass County, Minnesota

Z-17 141-28
Bk.7 Pg.16

1863 Johnson and Thornton, U.S. Deputy Surveyors, originally established this corner position while running the 10th Standard Parallel. The notes indicate a wood post was set to mark the corner position and the following witnesses: a 7 inch Spruce North 65 degrees West a distance of 5 links; and a 5 inch Aspen North 26 degrees East a distance of 5 links.

1912 County Surveyor's Record Book B pages 265-269 show survey by John Curo and Harry S. Todd, whereby Todd reestablished the section corner monumented on the 10th Standard Parallel for the entire South line of this township. These corner positions were determined proportionally between the Southeast and Southwest township corners. He set corner proportionally and marked the following bearing trees: a 14 inch Norway Pine stump South 70 degrees West a distance of 61.30 feet; and a 12 inch Norway stump North 75 degrees West a distance of 35.35 feet.

1917 J.H. Flynn, Deputy County Surveyor, County Survey Record 367, Book B page 592-593 shows Flynn measuring same distances as reported by Todd. Finding the Southeast corner of Section 35 monumented and that he monumented the Southwest corner of Section 34 this township.

1918 the U.S. General Land Office resurveyed portions of this township and in the process did not recover this corner. They used the Southwest and Southeast corners of the township to proportion the whole South line of the township.

1920's John Curo performed numerous surveys along the South line of this township in which he also proportioned in the Section and Quarter corners as noted by Todd. The Curo and Todd surveys differed slightly in overall dimensions. However, their theory and principles were the same.

1963 George Claydon surveys and prepares plat of AUDITOR'S PLAT OF LONGVILLE. This Auditor's plat does not specifically identify or denote the location of this corner. If the plat, however, is analyzed, one might develop an opinion on the location of this corner through the relationship of various other plat lines. This plat was not used in determining the location of this corner.

1986 U.S. Forest Service crews set an aerial target in the vicinity of this corner for the search and establishment of the true corner position. The target having coordinate values through the use of GPS on the Chippewa South Boundary Project Cadastral Survey U.S. Project Number 53-6392-8-219. This target allowed for the search and location of this corner.

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

Standard Southeast Corner Section 34, Township 141
North, Range 28 West, Cass County, Minnesota

Z-17 141-28
Bk.7 Pg.16

1988 on October 14 a Landecker-Stevenson & Associates crew searched for the corner. The following information was found and noted: no evidence of bearing trees or irons in area. Corner determined lost.

1989 on May 4 a Landecker-Stevenson & Associates crew set a 2 inch by 24 inch iron pipe with brass cap and plastic base with magnet at the lost, single proportion position between the monumented South Quarter corner of Section 34 and the monumented Southeast corner of Section 36 of said township along the arc of the 10th Standard Parallel. New bearing trees were marked as shown on front of this certificate. It was determined that this position resembles the single proportionate position on the standard parallel as determined by previous surveys from Curo, Todd and Flynn noted above.