CERTIFICATE OF LOCATION OF GOVERNMENT CORNER Northeast 1/16th Corner of Section 12 , Township 141N, Range 29W. , 5th P.M.	
STATE OF MINNESOTA, County of	
At the corner location shown on the sketch:	
On 7/27/87 found a 1" GLO brass cap monument	
☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)	
Onploced a	
SKETCH OF REFERENCE TIES	
A NOT TO SCALE	
	,
II" RED OAK SCRIBED "NE 1/16 S12 BT"	
Cui	
NEST	
NESTW- STEET	
The state of the s	
4" AND 5" BURR CAR SCRIBED "NE IVIG AT GLO RECORD BEARING AND DISTANCE GROWING OUT OF STUMP 9" MAPLE SCRIBED "NE IVIG SIZ BT"	
Statement of evidence relative to this corner location is on back of page. 317973	
I hereby certify that this document and the data	OFFICE OF THE COUNTY RECORDER
contained herein was prepared by me or under	County of
my direct supervision.	I hereby certify that this document was filed in the Co. Recorders, office at 2.55.M. on the
Well E. Care 1-22-90 SIGNATURE DATE	22day of January A.D., 19 90
Registration No. 11395	County Recorder Clauding Baylon
🗷 Land Surveyor	By,Deputy

DOCUMENT NO. ____

☑ County Surveyor

Statement of Evidence:

F-24

Northeast One-sixteenth Corner, Section 12, T.141N., R.29W., 5th PM

- 1918 U.S. General Land Office dependent resurvey set a 1"x 36" iron pipe with a marked brass cap for this corner and marked the following bearings: 8" Poplar N82½E 33 links and a 4" White Oak S68E 30 links.
- On July 27, Terry Freeman of the Cass County Surveyor's office and Curt Krause of the U.S. Forestry Service found monument in good condition. Cass County had previously chained into the corner from the east and to the north. The distances check well. The corner is at the northeast corner of the slope to the south and west, near the top of the ridge. Three large rocks were piled around the monument. Three new bearings were marked as shown on the front of this certificate.