| CERTIFICATE OF LOCATION OF GOVERNMENT CORNER                               |  |
|--|--|
| East Quarter Corner of Section 16 ,Township 143N ,Range 26W , 5th P.M.     |  |
| STATE OF MINNESOTA, County of  |  |
| At the corner location shown on the sketch:                                |  |
| ł  |  |
| M On 1-15-1990 found a 2" X 36" brass capped monument                      |  |
| ☑ left monument as found, ☐ lowered monument, ☐ removed monument (explain) |  |
| □ Onplaced d   |  |
| DATE   |  |
| Monument Marked SKETCH OF REFERENCE TIES not to scale                      |  |
| 1 4  | White  |
| 1/4<br> Nt S16   S15   | (1) 11" Oak<br>N36°E 213.70                      |
| 1 210 213  | (1969)   |
| 1922   |  |
| 4  | 9" Ash   |
|  | N51°E 161.48                                     |
| Steel Post   |  |
| •  | North 4.0  |
| (  | Steel Post<br>East 5.4                           |
| SEC. 16  | SEC. 15  |
|  |  |
| •  | Steel Post<br>South 8.6                          |
|  | South 8.6  |
|  |  |
|  |  |
|  |  |
|  |  |
|  | trees are scribed, painted with a 30d            |
|  | ke in side and USFS 54-3 tag.                    |
| Statement of evidence relative to this corner location is on back of page. |  |
| I hereby certify that this survey, plan or                                 | OFFICE OF THE COUNTY RECORDER                    |
| report was prepared by me or under my                                      | County ofCar                                     |
| direct supervision and that I am a duly                                    | I hereby certify that this document was filed in |
| Registered Land Surveyor under the laws of the State of Minnesota.         | the Co. Recorders office at 10:00 A.M. on the    |
| • •  | County Recorder Claudine Kaylar                  |
| William C. Osufer  | By   |
| Date <i>3/20/90</i> Registration No. <u>17767</u>                          | DOCUMENT NO. 319614                              |

## Statement of Evidence:

L13 East quarter corner section 16

1/4 Cor. 15 and 16 (E 1/4 Cor. Sec. 16)

- 1872 U.S. General Land Office survey set wood post for corner in bog, no references were noted:
- General Land Office survey, at corner of fences, bearing E. and S., the recognized and accepted position for corner, set a 36" X 2" iron post with brass cap and the following references:

  Elm 16" N 79 degrees 30 minutes E, 206 Links (135.96)
  Basswood 14" N 19 degrees W, 485 Links (320.10)
- 1969 U.S.F.S. found G.L.O. monument in good condition and 1922 BT
  Basswood 14" N 19 degrees W, 485 Links (320.10 feet) they added the following references:
  Ash 6" N 51 degrees E, 161.70 feet
  White Oak 10" N 36 degrees E, 213.60 feet
  Steel sign post with sign attached, North 2.9 feet
- 1-15-1990 Personnel from Kovanen & Osufsen Inc. found G.L.O. monument in good condition, and U.S.F.S. BT, add spike and paint;
  Ash 9" N 51 degrees E, 161.48 feet
  Steel sign post with sign attached, North 4.0 feet we added the following new witnesses:
  White Oak 11" N 36 degrees E, 213.70 feet
  Set 8' long steel sign post with sign attached, South 8.6 feet
  Set 8' long steel sign post with sign attached, East 5.4 feet

This position is not traceable to the original GLO corner, but accepted as corner for lack of further evidence.