CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
Northeast Corner of Section	,Township <u>143N</u> , Range <u>26W</u> , <u>_5th</u> P.M.
STATE OF MINNESOTA, County of	
At the corner location shown on the sketch:	
On found a	
☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)	
On 4-9-90 placed a 2" X 48" brass capped monument	
Monument Marked SKETCH OF REFERENCE TIES T143N R26W S23 S24 N- S26 S25	
1990 SEC. 23 RLS 17767 SEC. 23 5" Maple N63°W 63.79	SEC. 24 6" Birch N40°E 18.90
SEC. 26	North 2.8 Steel Post East 2.5 6" Birch S85°E 38.60 SEC. 25
6" Birch s32°W 83.75	
All trees are scribed, painted with a 30d bearings are true spike in side and USFS 54-3 tag.	
Statement of evidence relative to this corner location is on back of page.	
I hereby certify that this survey, plan or report was prepared by me or under my direct supervision and that I am a duly Registered Land Surveyor under the laws of the State of Minnesota. William C. Osufan. Date 8/22/90 Registration No. 17767	OFFICE OF THE COUNTY RECORDER County of

Statement of Evidence:

4-9-1990

R21 Northeast corner section 26

2.8 feet

Cor. 23,24,25 and 26 (NE Cor. Sec. 26)

1872 U.S. General Land Office survey set wood post for corner and the following references were noted: 6" N 31 degrees E, 12 Links (7.92 feet) 6" S 8 degrees W, 40 Links (26.40 feet) Spruce 8" N 53 degrees W, 50 Links (33.00 feet) Fir 5" S 60 degrees E. 30 Links (19.80 feet) Fir

1968 Curt Krause, USFS, chained to searched area from section corner to north, area has been recently cut off, no evidence of corner, or BT's found.

11-8-1989 Personnel from Kovanen & Osufsen Inc. traverse to area, area has been disturbed by road construction, no evidence of corner, or BT's found.

Personnel from Kovanen & Osufsen Inc. made an additional search of area, nothing found, set a 2" x 48" brass capped monument in lost position by double proportion method using found Northeast corner of Section 25, found North Quarter corner of Section 27. found Northeast corner of Section 35 and the reestablished Northeast corner of Section 23, mark the following witnesses: S 32 degrees W, 83.75 feet Maple 5" N 63 degrees W, 63.79 feet Birch 6" N 40 degrees E, 18.90 feet Birch 6" S 85 degrees E, 38.60 feet

Set 8' long steel sign post with sign attached, East 2.5 feet Set 8' long steel sign post with sign attached, North

This position is not traceable to the original GLO corner, but accepted as corner for lack of further evidence.