	1
CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
East Quarter Corner of Section 25 ,Township 143N , Ronge 26W , 5th P.M.	
STATE OF MINNESOTA, County of	
At the corner location shown on the sketch:	
On found a	
☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)	
∇ On 6/27/90 placed a 2 inch x 54 inch Brass Cap Monument over an 8 foot long steel fence post driven into swamp for corner.	
Monument marked SKETCH OF REFERENCE TIES	
T143N Not to	scale
1/4	
-N-98	
1990	7 inch Maple
' RLS 17767	8 foot steel fence N 61° E 96.26
₩ ₩	post, 3.5 feet North
10 inch Birch	
N 54° W 57.90	
GTG 35	CDG 20
SEC. 25	SEC. 30
	\mathfrak{S}
1	
	10 inch Birch S 63° E
	84.90
	ll trees are scribed, painted with a 30d
Bearings are true sp	pike in side and USFS 54-3 tag.
Statement of evidence relative to this corner location is on back of page. 32.5.146	
I hereby certify that this survey, plan or	OFFICE OF THE COUNTY RECORDER
report was prepared by me or under my	County of
direct supervision and that I am a duly	I hereby certify that this document was filed in
Registered Land Surveyor under the laws of the State of Minnesota.	the Co. Recorders office at 40 P.M. on the 21 day of November A.D., 19 90
	County Recorder Clanding Kaylan
Welliam C. Oofen	By My Deputy
Date 11/14/90 Registration No. 17767	DOCUMENT NO. 325146

Statement of Evidence:

T25 East quarter corner section 25

1/4 Cor. 25 and 30 (E 1/4 Cor. Sec. 25)

1872 U.S. General Land Office survey set wood post for corner and the following references were noted:
Tamarack 10" S 70 degrees E, 14 Links (9.24 feet)
Aspen 14" S 81 degrees W, 11 Links (7.26 feet)

7-19-1966 James Ekstrom, USFS, found no evidence of corner.

1976 BLM dependent resurvey, found no original evidence, at proportionate distance they set a 2.5"x 28" aluminum post, with aluminum cap, and witnessed as follows:
Birch 4" N 18 degrees W, 48 Links (31.68 feet)

11-2-1989 Personnel from Kovanen & Osufsen Inc. traversed to search area, no evidence of corner, or BT's found.

6-27-1990 Personnel from Kovanen & Osufsen Inc. set a 2" x 54" brass capped monument over an 8 foot steel fence post in swamp. This position is reestablished midway and on line between the recovered NE corner of section 25 and the recovered SE corner of section 25. The following witnesses were established:

Birch 10" N 54 degrees W, 57.90 feet Maple 7" N 61 degrees E, 96.26 feet

Birch 10" S 63 degrees E, 84.90 feet Set 8' long steel sign post with sign attached, North 3.5 feet

This position is not traceable to the original GLO corner, but accepted as corner for lack of further evidence.