Į	CERTIFICATE OF LOCATION	OF GOVERNMENT CORNER
	North Quarter Corner of Section 3 STATE OF MINNESOTA, County of Cass	,Township <u>142 N</u> ,Range <u>25 W</u> , <u>5th</u> P.M.
١		
At the corner location shown on the sketch:		
On 10/26/90 found o 2½ inch aluminum capped monument 8 inches above ground		
☑ left monument as found, ☐ lowered monument, ☐ removed monument (explain)		
	Onplaced a	
	Magnetic Decl: 5° East SKETCH OF RE Not to Scale (1983 USFS) 7" Maple -N- N 51 W 47.34'	horizontal to nail in side of tree
		(1976 BT) 12" Poplar N 47 E 10.06'
	(1976 BT)	7" Maple S 55 E 24.15'
	13" Poplar S 42 W 18.0'	Monument Stamped US Dept. of the Interior Unlawful to Disturb T143N R25W
	8' steel sign post 3.0' East. All trees are painted with red enam	1 S34 4S3 nel and 71 A2N
	marked with a 54-3 (Bearing Tree) t	tag. 1976 Cadastral Survey Bur. of Land Management
	Statement of evidence relative to this corner location is on back of page. 325280	
100	I hereby certify that this document and the data contained herein was prepared by me or under	OFFICE OF THE REGISTER OF DEEDS County ofCleur
	my direct supervision. Mul A Justile 1/28/90 Signature / Date	I hereby certify that this document was filed in the Reg. of Deeds office at 4.15M. on the 29 day of Movember A.D., 19 90
	Registration No. 17008	Register of Deeds Claudine Kaylur
	⊠ Land Surveyor, □ Professional Engineer	DOCUMENT NO. 325280
	☐ County Surveyor, ☐ County Engineer	DUCUMENT NO a _ a _ o _

North Quarter corner, Section 3, Township 142 North, Range 25 West, Cass County, Minnesota

A-15

1871 Walker, Putnam and Allen, U.S. Deputy Surveyors, originally established this corner position while running the line between Townships 142 and 143 North, Range 25 West. The notes indicate a wood post was set to mark the corner position and the following witnesses: a 6 inch Maple North 62 degrees East a distance of 11 links; and an 8 inch Fir South 34 degrees West a distance of 16 links.

1976 Bureau of Land Management dependent resurvey reestablished this corner at the single proportionate position between the Meander corner on the West side of Willow Lake and the North Quarter corner of Section 4. A 2 and 1/2 inch by 28 inch aluminum pipe with an aluminum cap was set to mark the corner. The following bearing trees were marked: a 12 inch Aspen North 42 degrees East a distance of 15 links (9.9 feet); and a 12 inch Aspen South 45 degrees West a distance of 27 links (17.82 feet).

1979 Gary Stevenson & Associates, Inc., survey crew found the 1976 Bureau of Land Management monuments around Section 34, Township 143 North, Range 25 West. They were used to subdivide said section.

1983 U.S. Forest Service personnel found the 1976 Bureau of Land Management 2 and 1/2 inch capped aluminum post and both 1976 Aspen bearing trees. They marked a 6 inch Maple bearing tree North 51 degrees West a distance of 47.34 feet and set a steel sign post West 3.0 feet.

1990 on October 26, a Landecker & Associates, Inc., survey crew found the 2 and 1/2 inch aluminum capped monument 8 inches above ground as set by the Bureau of Land Management in 1976. Bearing trees are marked as shown and a steel sign post was set as noted on front of this certificate.