

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


MEANDER Corner of Section 20-21, Township 143, Range 25, 5th P.M.
 STATE OF MINNESOTA, County of CASS

At the corner location shown on the sketch:

- On 1989 found a 2" x 60" IRON PIPE WITH BRASS CAP
DATE
- left monument as found, lowered monument, removed monument (explain)
- On _____ placed a _____
DATE

NOT TO SCALE

SKETCH OF REFERENCE TIES



8' STEEL SIGN POST NORTH 5.00

T.143N. R.25W.
 MC
 S20 S21
 1965
 6807

NOTE: ALL BT'S ARE BLAZED, SCRIBED AND PAINTED WITH RED ENAMEL PAINT WITH BT SIGNS, AND ALL MEASUREMENTS ARE HORIZONTAL TO SPIKE IN SIDE OF TREE

Statement of evidence relative to this corner location is on back of page.

326337

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Walter C. Linn
SIGNATURE

1-22-91
DATE

Registration No. 11395

- Land Surveyor
- County Surveyor

OFFICE OF THE COUNTY RECORDER

County of Cass

I hereby certify that this document was filed in the Co. Recorders office at 9:10 A. M. on the 25 day of January A.D., 1991

County Recorder Cloudeine Kayler
 By ms, Deputy

DOCUMENT NO. 326337

Statement of Evidence:

QR 9 Meander Corner to Sec. 20-21, T.143N., R.25W.

1872 Original survey by Hayward and Griffin, set a wood post and marked bt's as follows: 3" Spruce N28E 31.5lks.

1913 John Curo set corner, in County record book B, pages 4-11 he states that they found original bearing trees for the northeast corner, and the east quarter corner to section 20, and that they searched for the Meander corner and found the remains of a tree that could possibly have been a bearing tree as the distance and direction fit closely to a point on the lake shore, but the distance south from the quarter corner was 216.88 feet short, so he set a post on line with the section corner and the quarter corner and at the shore of the lake. He did not mark any bearing trees.

1965 Bill Okerman, USFS, found a 2" iron pipe at the shore of Vermillion Lake and set a 2"x60" galv. pipe with brass cap and a steel sign post and marked a 17" W. pine N28W 149 lks. Recorded in book 2, page 24 of USFS restoration notes.

1976 B.L.M. making a dependent resurvey of part of the township found and accepted the brass cap set by the USFS. Their field notes show that there is a 1 minute of angle bend in the section line at the quarter corner and the pipe was supposed to have been set on a straight line in 1913, and their distance south from the quarter corner is about 1 foot different.

1979 Milo Steffan, USFS, filed a certificate on the 1965 perpetuation of this corner.

1989 The USFS used this corner as part of a traverse around section 28.

1990 Walt Curo accepts the brass cap monument as a reference Monument for the Meander Corner.